



PT. INSPEKTINDO SINERGI PERSADA
SERVICE TIMESHEET PAR

PT. Medco E & P
Contract Number : 3510007418
Location : Rimau Blok

Periode : 17 - 23 JULI 2023

No.	Descriptions	UOM	Jul-23							Total	Job Description
			17	18	19	20	21	22	23		
1	Jasa Radiografi Test	Days	1	1	1	1	1	1	1	7	1. Radiography Test Flowline 3" & 2" KS#57 Cluster P
2	Jasa Dye Penetrant Test	Joints	-	3	7	4	-	-	-	14	1. Dye Penetrant Test Trunkline 8" Cluster BA, BB 2. Dye Penetrant Test Flowline 3" KS#57 Cluster P 3. Radiography Test Flowline 3" & 2" Cluster P 4. Radiography Test Trunkline 8" Cluster BA, BB
3	Jasa Ultrasonic Test	Days								0	
4	Jasa Magnetic Particle Test	Days								0	
5	Jasa Holiday Test	Days								0	
6	Jasa Hydrotest Pipeline/Flowline * Prehydrotest dilakukan oleh Perusahaan	AU								0	1. Dye Penetrant Test Tarikan RIB di Yard C 2. Radiography Test Trunkline 8" Cluster AI, AJ 3. Radiography Test Trunkline WI 6" Cluster O, AU
7	Jasa Hydrotest Pipeline/Flowline * Prehydrotest dilakukan oleh Kontraktor	AU								0	
8	Hydrotest Piping system dalam station	AU								0	
9	Jasa Sewa Perahu Motor	Days								0	
Consumable Usage Summary											
No.	DESCRIPTION	UOM	Jul-23							Total	
			17	18	19	20	21	22	23		
1	Film 4x10"	EA	14	5	2	-	20	-	-	41	1. Radiography Test Chamber Separator Semoga 2. Radiography Test Trunkline WI 6" Cluster O, AU
2	Film 4x15"	EA	-	12	24	12	-	-	27	75	
Personnel											
No.	Name	Position	Working Period	Remarks							
1	FITER RONALD	COORDINATOR/IR	17 - 23 JULI 2023	7 Day							
2	ANSYORI	PPR	17 - 23 JULI 2023	7 Day							
3	RITO SEPTIANDI	OR/MT/PT	17 - 23 JULI 2023	7 Day							
4	MARWAN	OR/MT/PT	17 - 23 JULI 2023	7 Day							
5	AKBAR	ADM	17 - 23 JULI 2023	7 Day							
6	RIKI SAPUTRA	DRIVER	17 - 23 JULI 2023	7 Day							

MINGGU BERSIH DI DALAM KAJI STATION


Prepared by:

Reviewed by:

Approved by:



Name : **AKBAR**
Date: 30 JULI 2023



Name : **TEDDY MANDALA RAYA/ DODIK HENDRA DIANTORO**
Lead of PAR - Rimau Block

2/8/23

PT. INSPEKTINDO SINERGI PERSADA
SERVICE TIMESHEET PAR




PT. Medco E & P
Contract Number : 3510007418
Location : Rimau Blok

Periode : 24 - 30 JULI 2023



No.	Descriptions	UOM	Jul-23							Total	Job Description
			24	25	26	27	28	29	30		
1	Jasa Radiografi Test	Days	1	1	1	1	1	1	1	7	1. Radiography Test Trunkline 8" Cluster E 2. Radiography Test Trunkline 8" Cluster G
2	Jasa Dye Penetrant Test	Joints	-	-	-	-	2	2	-	4	
3	Jasa Ultrasonic Test	Days								0	
4	Jasa Magnetic Particle Test	Days								0	1. Radiography Test Trunkline WI 6" Cluster O, AU
5	Jasa Holiday Test	Days								0	
6	Jasa Hydrottest Pipeline/Flowline <i>* Prehydrottest dilakukan oleh Perusahaan</i>	AU								0	1. Radiography Test Trunkline WI 6" Cluster O, AU
7	Jasa Hydrottest Pipeline/Flowline <i>* Prehydrottest dilakukan oleh Kontraktor</i>	AU								0	
8	Hydrottest Piping system dalam station	AU								0	1. Radiography Test Trunkline WI 6" Cluster O, AU
9	Jasa Sewa Perahu Motor	Days								0	
Consumable Usage Summary											
No.	DESCRIPTION	UOM	Jul-23							Total	
1	Film 4x10"	EA	-	7	12	33	6	22	-	80	1. Radiography Test Line Test 4" Cluster F, G, H, Y 2. Radiography Test Trunkline WI 6" Cluster O, AU
2	Film 4x15"	EA	6	-	-	-	-	-	-	6	
Personnel											
No.	Name	Position	Working Period	Remarks							
1	FITER RONALD	COORDINATOR/AR	24 - 30 JULI 2023	7 Day							
2	ANSYORI	PPR	24 - 30 JULI 2023	7 Day							
3	RITO SEPTIANDI	OR/MT/PT	24 - 30 JULI 2023	1 Day							
4	MARWAN	OR/MT/PT	24 - 30 JULI 2023	7 Day							
5	AKBAR	ADM	24 - 30 JULI 2023	7 Day							
6	RIKI SAPUTRA	DRIVER	24 - 30 JULI 2023	7 Day							
7	PETRUS HARRY NATALDO	OR/MT/PT	24 - 30 JULI 2023	7 Day							

MINGGU BERSIH DI DALAM KAJI STATION

Prepared by:  Name : AKBAR
 Reviewed by:  Eka Chandra/William
 Supervisor of PAR
 Approved by:  Name : TEDDY MANDALA RAYA/ DODIK HENDRA DIANTORO
 Lead of PAR - Rimau Block
 Date: 30 JULI 2023



PT. INSPEKTINDO SINERGI PERSADA
Raising Safety Standards
Inspection Services


PT. INSPEKTINDO SINERGI PERSADA
SERVICE TIMESHEET PAR


PT. Medco E & P
Contract Number : 3510007418
Location : Rimau Blok

Periode : 31 JULI 2023

No.	Descriptions	UOM	Jul-23							Total	Job Description
			31								
1	Jasa Radiografi Test	Days	1						1	1. Dye Penetrant Test Trunkline WI 6" Cluster O, AU 2. Radiography Test Trunkline WI 6" Cluster O, AU 3. Radiography Test Flowline 3" KS#107 Cluster O	
2	Jasa Dye Penetrant Test	Joints	2						2		
3	Jasa Ultrasonic Test	Days							0		
4	Jasa Magnetic Particla Test	Days							0		
5	Jasa Holiday Test	Days							0		
6	Jasa Hydrotest Pipeline/Flowline * Prehydrotest dilakukan oleh Perusahaan	AU							0		
7	Jasa Hydrotest Pipeline/Flowline * Prehydrotest dilakukan oleh Kontraktor	AU							0		
8	Hydrotest Piping system dalam station	AU							0		
9	Jasa Sewa Perahu Motor	Days							0		
Consumable Usage Summary											
No.	DESCRIPTION	UOM	Jul-23							Total	
			31								
1	Film 4x10"	EA	23							23	
2	Film 4x15"	EA	-							0	
Personnel											
No.	Name	Position	Working Period	Remarks							
1	FITER RONALD	COORDINATOR/AR	31 JULI 2023	1 Day							
2	ANSYORI	PPR	31 JULI 2023	1 Day							
3	PETRUS HARRY NATALDO	OR/MT/PT	31 JULI 2023	1 Day							
4	MARWAN	OR/MT/PT	31 JULI 2023	1 Day							
5	AKBAR	ADM	31 JULI 2023	1 Day							
6	RIKI SAPUTRA	DRIVER	31 JULI 2023	1 Day							

Prepared by: 
Name : AKBAR
Date: 31 JULI 2023

Reviewed by: 
Name : Eka Chandra/William
Supervisor of PAR



Approved by: 
Name : TEDDY MANDALA RAYA/ DODIK HENDRA DIANTORO
Lead of PAR, Rimau Block
7/8/23

PT. INSPECTINDO SINERGI PERSADA
SERVICE TIMESHEET PAR

PT. Medco E & P
Contract Number : 3510007418
Location : Rimau Blok

Periode : 01 - 06 AGUSTUS 2023



No.	Descriptions	UOM	Aug-23							Total	Job Description
			1	2	3	4	5	6			
1	Jasa Radiografi Test	Days	-	1	1	1	1	1	1	6	
2	Jasa Dye Penetrant Test	Joints	-	2	-	-	-	-	-	2	
3	Jasa Ultrasonic Test	Days	-	-	-	-	-	-	-	0	
4	Jasa Magnetic Particle Test	Days	-	-	-	-	-	-	-	0	1. Radiography Test Trunkline 8" Cluster AI, AJ
5	Jasa Holiday Test	Days	-	-	-	-	-	-	-	0	2. Radiography Test Trunkline 8" Cluster B, BC
6	Jasa Hydrotest Pipeline/Flowline * Prehydrotest dilakukan oleh Perusahaan	AU	-	-	-	-	-	-	-	0	3. Radiography Test Line Test 4" Cluster F, G, H, Y
7	Jasa Hydrotest Pipeline/Flowline * Prehydrotest dilakukan oleh Kontraktor	AU	-	-	-	-	-	-	-	0	4. Radiography Test Flowline 3" KS#107 Cluster O
8	Hydrotest Piping system dalam station	AU	-	-	-	-	-	-	-	0	1. Dye Penetrant Test Line Test 4" Cluster F, G, H, Y
9	Jasa Sewa Perahu Motor	Days	-	-	-	-	-	-	-	0	2. Radiography Test Trunkline 8" Cluster AI, AJ
Consumable Usage Summary											
No.	DESCRIPTION	UOM	Aug-23							Total	
			1	2	3	4	5	6			
1	Film 4x10"	EA	-	3	-	45	4	18	-	70	1. Radiography Test Trunkline 8" Cluster B, BC
2	Film 4x15"	EA	-	24	10	3	30	14	-	81	2. Radiography Test Line Test 4" Cluster Z
Personnel											
No.	Name	Position	Working Period	Remarks							
1	FITER RONALD	COORDINATOR/AR	01 - 06 AGUSTUS 2023	6 Day							
2	ANSYORI	PPR	01 - 06 AGUSTUS 2023	6 Day							
3	PETRUS HARRY NATALDO	OR/MT/PT	01 - 06 AGUSTUS 2023	6 Day							
4	MARWAN	OR/MT/PT	01 - 06 AGUSTUS 2023	6 Day							
5	AKBAR	ADM	01 - 06 AGUSTUS 2023	6 Day							
6	ANDY ANTONY	AR	01 - 06 AGUSTUS 2023	6 Day							
7	RIKI SAPUTRA	DRIVER	01 - 06 AGUSTUS 2023	6 Day							
MINGGU BERSIH											
Prepared by:  Approved by:  Name : AKBAR PERTINDO SINERGI PERSADA Name : TEDDY MANDALA / DODIK HENDRA D Date: 06 AGUSTUS 2023 Lead of PAR / Rimau Block											


PT. INSPECTINDO SINERGI PERSADA
SERVICE TIMESHEET PAR

PT. Medco E & P
Contract Number : 3510007418
Location : Rimau Blok



Periode : 07 - 13 AGUSTUS 2023

No.	Descriptions	UOM	Aug-23							Total	Job Description
			7	8	9	10	11	12	13		
1	Jasa Radiografi Test	Days	1	1	1	1	1	1	1	7	1. Dye Penetrant Test Flowline 2" KS#140 Cluster K 2. Dye Penetrant Test Line Test 4" Cluster AN, AD 3. Radiography Test Flowline 3" KS#140 Cluster K
2	Jasa Dye Penetrant Test	Joints	3	2	2	2	-	-	-	9	
3	Jasa Ultrasonic Test	Days								0	
4	Jasa Magnetic Particle Test	Days								0	1. Dye Penetrant Test Flowline WI 4" Cluster M 2. Radiography Test Flowline WI 4" & 3" Cluster M 3. Radiography Test Flowline 3" KS#142 Cluster X
5	Jasa Holiday Test	Days								0	
6	Jasa Hydrotest Pipeline/Flowline * Prehydrotest dilakukan oleh Perusahaan	AU								0	
7	Jasa Hydrotest Pipeline/Flowline * Prehydrotest dilakukan oleh Kontraktor	AU								0	
8	Hydrotest Piping system dalam station	AU								0	1. Dye Penetrant Test Flowline 3" KS#140 Cluster K 2. Dye Penetrant Test Flowline 3" KS#142 Cluster X
9	Jasa Sewa Perahu Motor	Days								0	
Consumable Usage Summary											
No.	DESCRIPTION	UOM	Aug-23							Total	
			7	8	9	10	11	12	13		
1	Film 4x10"	EA	3	43	-	27	9	12	-	94	
2	Film 4x15"	EA	-	-	-	6	19	1	-	26	
Personnel											
No.	Name	Position	Working Period	Remarks							
1	FITER RONALD	COORDINATOR/AR	07 - 13 AGUSTUS 2023	1 Day							
2	ANSYORI	PPR	07 - 13 AGUSTUS 2023	7 Day							
3	PETRUS HARRY NATALDO	OR/MT/PT	07 - 13 AGUSTUS 2023	7 Day							
4	MARWAN	OR/MT/PT	07 - 13 AGUSTUS 2023	7 Day							
5	AKBAR	ADM	07 - 13 AGUSTUS 2023	7 Day							
6	ANDY ANTONY	AR	07 - 13 AGUSTUS 2023	7 Day							
7	RIKI SAPUTRA	DRIVER	07 - 13 AGUSTUS 2023	7 Day							

Prepared by :  Name : **AKBAR**
 Reviewed by :  Name : **WILLIAM / EKA CHANDRA**
 Approved by :  Name : **TEDDY MANDALA / DODIK HENDRA D**
 Lead of PAR - Rimau Block

STAND BY




Date: 13 AGUSTUS 2023

Supervisor of PAR



PT. INSPEKTINDO SINERGI PERSADA
 SERVICE TIMESHEET PAR
 PT. Medco E & P
 Contract Number : 3510007418
 Location : Rimau Blok

Periode : 14 - 20 AGUSTUS 2023

No.	Descriptions	UOM	Aug-23							Total	Job Description
			14	15	16	17	18	19	20		
1	Jasa Radiografi Test	Days	1	1	1	1	1	1	1	7	1. Radiography Test Trunkline 8" Cluster AI, AJ 2. Radiography Test Trunkline 8" Cluster B, BC 3. Radiography Test Line Test 4" Cluster A 4. Radiography Test Spool Test Clamp 5. Radiography Test Trunkline 8" Cluster AZ
2	Jasa Dye Penetrant Test	Joints	-	-	6	-	5	4	-	15	
3	Jasa Ultrasonic Test	Days								0	
4	Jasa Magnetic Particle Test	Days								0	
5	Jasa Holiday Test	Days								0	1. Radiography Test Trunkline 8" Cluster AI, AJ 2. Radiography Test Trunkline 8" Cluster B, BC
6	Jasa Hydrotelst Pipeline/Flowline * Prehydrotelst dilakukan oleh Perusahaan	AU								0	
7	Jasa Hydrotelst Pipeline/Flowline * Prehydrotelst dilakukan oleh Kontraktor	AU								0	1. Dye Penetrant Test Trunkline 4" Cluster AZ 2. Dye Penetrant Test Line Gas Compressor Plant Semoga 3. Radiography Test Spool Dicharge WIP 04 4" Kaji
8	Hydrotelst Piping system dalam station	AU								0	4. Radiography Test Line 2", 3" & 4" Gas Compressor Semoga 5. Radiography Test Trunkline 8" Cluster AI, AJ & B, BC
9	Jasa Sewa Perahu Motor	Days								0	
Consumable Usage Summary											
No.	DESCRIPTION	UOM	Aug-23							Total	
1	Film 4x10"	EA	4	-	25	-	3	25	-	57	
2	Film 4x15"	EA	16	12	12	-	-	24	-	64	
Personnel											
No.	Name	Position	Working Period							Remarks	
1	ANSYORI	PPR	14 - 20 AGUSTUS 2023							7 Day	
2	PETRUS HARRY NATALDO	OR/MT/PT	14 - 20 AGUSTUS 2023							7 Day	
3	MARWAN	OR/MT/PT	14 - 20 AGUSTUS 2023							7 Day	
4	AKBAR	ADM	14 - 20 AGUSTUS 2023							7 Day	
5	ANDY ANTONY	AR	14 - 20 AGUSTUS 2023							7 Day	
6	DIDIT KURNIAWAN	DRIVER	14 - 20 AGUSTUS 2023							5 Day	
7	RIKI SAPUTRA	DRIVER	14 - 20 AGUSTUS 2023							2 Day	
Prepared by :											
Reviewed by :											
 Name : WILLIAM / EKA CHANDRA Supervisor of PAR											
 Name : TEDDY MANDALA / DODIK HENDRA D Lead of PAR - Rimau Block											
 Name : AKBAR Date : 20 AGUSTUS 2023											