

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:
 Period:
 Day Rate:
 Per Diem Rate:

Customer:
 Contract/ PO Non:
 Rig / Well:

Date:
 Our Ref:
 Form No:

Billing Date	Rig / Loc*	Time*	ACTIVITY (Reguler)	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
16-Apr-24	Manggar Base	08:00-17:00	Inspected of Under Reamer - CATCHER, 11625-17500 RHINO XS2 - 9428801-004 - (MPI Inspection), Reamer - Catcher Cap, 11625-17500 Rhino XS2 - AA4544A - (MPI Inspection), Reamer - LOWER MANDREL, 11625-17500 RHINO XS2 - AJ86950 - (MPI Inspection), Reamer - Lower Mandrel Cap, 11625-17500 Rhino XS2 - 4582488751-4-1 - (MPI Inspection), Reamer - BORE GUIDE SLEEVE, 11625-16000 RHINO XS AND XS2 - AJ89642 - (MPI Inspection), Reamer - DEACTIVATION OUTER SLEEVE, 11625-17500 RHINO XS2 - AK03495 - (MPI Inspection), Reamer - DEACTIVATION INNER SLEEVE, 11625-17500 RHINO XS2 - AJ80703 - (MPI Inspection), Reamer - ACTIVATION SLEEVE FOR 11625 RHINO XS2 - AK03964 - (MPI Inspection)	8	WCD_BDT_RR11625_10386103-002_16APR24		BDT	SMITH TOOL INDONESIA
17-Apr-24	Manggar Base	08:00-17:00	Inspected of Rog Bit 17 1/2" HS - QG 0345 - (VTI Inspection and Withness with QC PHKT), Rog Bit 17 1/2" HS - QG 0346 - (VTI Inspection and Withness with QC PHKT), Rog Bit 8 1/2" HS - QG 0369 - (VTI Inspection and Withness with QC PHKT), Rog Bit 8 1/2" HS - QG 0368 - (VTI Inspection and Withness with QC PHKT)	8	To Be Created		BDT	
TOTAL (hours)				16				

Saftiadi Akbar Riswan
 Personnel In Attendance

* If Applicable

 Saftiadi
 ISP Inspector

Cristoper
 SLB Maintenance Technician

Adi Rahmadite
 SLB Maintenance Supervisor