

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: Satliadi Lamboh, Faro Mangara
 Period: June-July 2023
 Day Rate: _____
 Per Diem Rate: _____

Customer: PT. Schlumberger Indonesia - D&M
 Contract/ PO No: _____
 Rig / Well: Duri Base

Date: _____
 Our Ref: _____
 Form No: _____

Billing Date	Rig / Loc ^a	Time ^a	ACTIVITY (OVERTIME)	Hours	WO Number	BILLING			Company Representative Signature
						BORG	Segment		
1-Jul-23	Duri Base	10:00-22:00	String stab 9 1/2"HS_BMS 10S02 (MPI Inspection), Near Bit, Steel, Integral Spiral Blade - 12 1/4"HS_GP 6924-44 (MPI Inspection), String stab 9 7/8"HS_GP 6924-82 (MPI Inspection), Near bit stab 12 1/4"HS_GP 6924-46 (MPI Inspection), String stab 9 3/8"HS_GP 6924-87 (MPI Inspection), Bottle Neck_SBD 1317 (MPI Inspection), Bottle Neck_GP 6968-37 (MPI Inspection)	11 ✓	WCM_020723_240-256_DURI		D&M	<i>[Signature]</i>	
2-Jul-23	Duri Base	08:00-18:00	String stab 1 1/4"HS_GP 7127-31 (MPI Inspection), String stab 9 3/8"HS_83297 H (MPI Inspection), String stab 9 1/2"HS_BBS 592803 (MPI Inspection), String stab 9 3/4"HS_BBS 527402 (MPI Inspection), 1 Set Mud Motor ASSY A675_18815 (MPI Inspection), 1 Set Mud Motor LILIN ASSY 825_20629 (MPI Inspection), String stab 7 1/2"HS_GP 6924-109 (MPI Inspection)	9 ✓	WCM_020723_240-256_DURI		D&M	<i>[Signature]</i>	
3-Jul-23	Duri Base	17:00-21:00	NMPC 6" SBD 3822 (DPI Inspection), JAR NOV_474-651289 (MPI Inspection), 1 Set Mud Motor ASSY 675_05488 (MPI Inspection), Bottle Neck_JCP23-OSS-006 (MPI Inspection), EMT 6.5 RYTON GAP SUB_4-1/2IF-GSBD044R (MPI Inspection), Float sub_SSD 9825 (MPI Inspection)	4 ✓	To Be Created		D&M	<i>[Signature]</i>	
4-Jul-23	Duri Base	17:00-21:00	SFSA 6, 1793 (DPI Inspection), Hole Operer & 1/2"HS_HQ0850-03-05-23-SA (MPI Inspection), Bullnose_BU0850 RP 01_09-22-SA (MPI Inspection), Crossover_SBD 14651 (MPI Inspection), Non Mag Float sub_NN (MPI Inspection), 1 Set Mud Motor ASSY 958_06220015 (MPI Inspection), 1 Set Mud Motor ASSY 825_180456 (MPI Inspection), NMDC 6" _AMAS 6767865 (MPI Inspection)	4 ✓	To Be Created		D&M	<i>[Signature]</i>	
5-Jul-23	Duri Base	17:00-22:00	2 ea URRB 825_NN (MPI Inspection), Transmission Shaft 825_1801017 (MPI Inspection), Transmission Shaft 825_1801005 (MPI Inspection), Splined Mandrel 825_1802028 (MPI Inspection), Bearing Nut 825_NN (MPI Inspection), Bearing Housing 825_1802007 (MPI Inspection), Splined Mandrel 825_1802028, LRRB_NN (MPI Inspection), Drive sub 825_0070717 (MPI Inspection), NMDC_99476H (MPI Inspection)	5 ✓	To Be Created		D&M	<i>[Signature]</i>	
TOTAL (hours)				33 ✓					

* If Applicable

[Signature]
 Satliadi Lamboh, Faro
 Personnel In Attendance

[Signature]
 Satliadi
 ISP Inspector

[Signature]
 SLB Maintenance Technician

[Signature]
 Anson Kimman
 SLB Maintenance Supervisor

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: Sattialdi Lamboh, Faro Mangara
 Period: June-July 2023
 Day Rate: _____
 Per Diem Rate: _____

Customer: PT. Schlumberger Indonesia - D&M
 Contract/ PO No: _____
 Rig / Well: Duri Base

Date: _____
 Our Ref: _____
 Form No: _____

Billing Date	Rig / Loc	Time*	ACTIVITY (OVERTIME)	Hours	WO Number	BILLING			Company Representative Signature
						BORG	Segment		
1-Jul-23	Duri Base	10:00-22:00	String stab 9 1/2"HS_BMS 10S02 (MPI Inspection), Near Bit, Steel, Integral Spiral Blade - 12 1/4"HS_GP 6924-44 (MPI Inspection), String stab 9 7/8"HS_GP 6924-82 (MPI Inspection), Near bit stab 12 1/4"HS_GP 6924-46 (MPI Inspection), String stab 9 3/8"HS_GP 6924-87 (MPI Inspection), Bottle Neck_SBD 1317 (MPI Inspection), Bottle Neck_GP 6968-37 (MPI Inspection)	11 ✓	WCM_020723_240-256_DURI		D&M	<i>[Signature]</i>	
2-Jul-23	Duri Base	08:00-18:00	String stab 1 1/4"HS_GP 7127-31 (MPI Inspection), String stab 9 3/8"HS_83297 H (MPI Inspection), String stab 9 1/2"HS_BBS 582803 (MPI Inspection), String stab 9 3/4"HS_BBS 527402 (MPI Inspection), 1 Set Mud Motor ASSY A675_18815 (MPI Inspection), 1 Set Mud Motor LILIN ASSY 825_20629 (MPI Inspection), String stab 7 1/2"HS_GP 6924-109 (MPI Inspection)	9 ✓	WCM_020723_240-256_DURI		D&M	<i>[Signature]</i>	
3-Jul-23	Duri Base	17:00-21:00	NMPC 6" SBD 3822 (DPI Inspection), JAR NOV_474-651289 (MPI Inspection), 1 Set Mud Motor ASSY 675_05488 (MPI Inspection), Bottle Neck_JCP23-OSS-006 (MPI Inspection), EMT 6.5 RYTON GAP SUB_4-1/2IF -GSB0044R (MPI Inspection), Float sub_SSD 9825 (MPI Inspection)	4 ✓	To Be Created		D&M	<i>[Signature]</i>	
4-Jul-23	Duri Base	17:00-21:00	SFSA 6, 1793 (DPI Inspection), Hole Operer & 1/2"HS_HQ0850-03-05-23-SA (MPI Inspection), Bullnose_BU0850 RP 01_09-22-SA (MPI Inspection), Crossover_SBD 14651 (MPI Inspection), Non Mag Float sub_NN (MPI Inspection), 1 Set Mud Motor ASSY 958_06220015 (MPI Inspection), 1 Set Mud Motor ASSY 825_180456 (MPI Inspection), NMDC 6" AIVAS 6767665 (MPI Inspection)	4 ✓	To Be Created		D&M	<i>[Signature]</i>	
5-Jul-23	Duri Base	17:00-22:00	2 ea URRB 825_NN (MPI Inspection), Transmission Shaft 825_1801017 (MPI Inspection), Transmission Shaft 825_1801005 (MPI Inspection), Splined Mandrel 825_1802028 (MPI Inspection), Bearing Nut 825_NN (MPI Inspection), Bearing Housing 825_1802007 (MPI Inspection), Splined Mandrel 825_1802028, LRRB_NN (MPI Inspection), Drive sub 825_0070717 (MPI Inspection), NMDC_99476H (MPI Inspection)	5 ✓	To Be Created		D&M	<i>[Signature]</i>	
TOTAL (hours)				33					

* If Applicable

[Signature]
 Sattialdi Lamboh, Faro
 Personnel In Attendance

[Signature]
 Sattialdi
 ISP Inspector

[Signature]
 SLB Maintenance Technician

[Signature]
 Anson Kimman
 SLB Maintenance Supervisor

**PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET**



Personnel In Attendance: Satriadi Lamhot, Fero Mangara
 Period: June-July 2023
 Day / Rate: _____
 Per Diem Rate: _____

Customer: PT Schlumberger Indonesia - D&M
 Contract / PO No.: _____
 Rig / Well: Duri Base

Date: _____
 Our Ref: _____
 Form No.: _____

Billing Date	Rig / Loc*	Time*	ACTIVITY (REGULER)	BILLING				
				Hours	WO Number	BORG	Segment	Company Representative Signature
3-Jul-23	Duri Base	08:00-17:00	Blank Sleeve_2210004_(MPI Inspection), String stab 7 1/2"HS_GP 6924-106_(MPI Inspection),String stab 7 3/4"HS_GP 6924-01_(MPI Inspection), 1 Set Mud Motor LILIN ASSY 962_08220011_(MPI Inspection), NMDIC 6" _AVMAS 6757836_(DPI Inspection), 1 Set Mud Motor LILIN ASSY 825_0521020_(MPI Inspection),	8	To Be Created		D&M	<i>[Signature]</i>
4-Jul-23	Duri Base	08:00-17:00	Bottle Neck_QOP23-OSS-002_(MPI Inspection), String stab 7 3/4"HS_10153407_(MPI Inspection), String stab 7 7/8"HS_83335 H_(MPI Inspection), 1 Set Mud Motor ASSY 675_08220024GY / LL_(MPI Inspection), SPSA 6_1792_(MPI Inspection),	8	To Be Created		D&M	<i>[Signature]</i>
5-Jul-23	Duri Base	08:00-17:00	Stator Tube 862_020006_(MPI Inspection), Tob sub 825_1802009_(MPI Inspection), Tob sub 625_1802011_(MPI Inspection), Catcher sub 825_0040918_(MPI Inspection), Adjusting ring 825_1802003_(MPI Inspection), Rotor Coupling 825_1708009_(MPI Inspection), Shaft Coupling 825_1708009_(MPI Inspection), Shaft Coupling 825_1708003_(MPI Inspection)	8	To Be Created		D&M	<i>[Signature]</i>
6-Jul-23	Duri Base	08:00-17:00	Offset Housing 825_1801003_(MPI Inspection), Bearing Housing 825_1802001_(MPI Inspection), Stator Adapter 825_1801023_(MPI Inspection), Sleeve stab 12 1/8"HS_LILIN 2_(MPI Inspection), Bearing section 825_0140718_(MPI Inspection), String stab 10-3/8" HS - 900-2001-4-150650_(MPI Inspection)	8	To Be Created		D&M	<i>[Signature]</i>
7-Jul-23	Duri Base	08:00-17:00	Mud Motor End to end LL-210-1707007_(MPI Inspection)	8	To Be Created		D&M	<i>[Signature]</i>
TOTAL (hours)				40				

* If Applicable

[Signature]
 Satriadi Lamhot, Fero
 Personnel In Attendance

[Signature]
 Satriadi
 ISP Inspector

[Signature]
 Andy
 SLB Maintenance Technician

[Signature]
 Anson Kimmom
 SLB Maintenance Supervisor

**PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET**



Personnel In Attendance: Satriadi Lamhot, Fero Mangara
 Period: June-July 2023
 Day / Rate: _____
 Per Diem Rate: _____

Customer: PT Schlumberger Indonesia - D&M
 Contract / PO No.: _____
 Rig / Well: _____
 Duri Base _____

Date: _____
 Our Ref: _____
 Form No.: _____

Billing Date	Rig / Loc*	Time*	ACTIVITY (REGULER)	BILLING				
				Hours	WO Number	BORG	Segment	Company Representative Signature
3-Jul-23	Duri Base	08:00-17:00	Blank Sleeve_2210004_(MPI Inspection), String stab 7 1/2"HS_GP 6924-106_(MPI Inspection),String stab 7 3/4"HS_GP 6924-01_(MPI Inspection), 1 Set Mud Motor LILIN ASSY 962_08220011_(MPI Inspection), NMDIC 6" _AVMAS 6757836_(DPI Inspection), 1 Set Mud Motor LILIN ASSY 825_0521020_(MPI Inspection),	8	To Be Created		D&M	<i>[Signature]</i>
4-Jul-23	Duri Base	08:00-17:00	Bottle Neck_QOP23-OSS-002_(MPI Inspection), String stab 7 3/4"HS_10153407_(MPI Inspection), String stab 7 7/8"HS_83335 H_(MPI Inspection), 1 Set Mud Motor ASSY 675_08220024GY / LL_(MPI Inspection), SPSA 6_1792_(MPI Inspection),	8	To Be Created		D&M	<i>[Signature]</i>
5-Jul-23	Duri Base	08:00-17:00	Stator Tube 862_020006_(MPI Inspection), Tob sub 825_1802009_(MPI Inspection), Tob sub 625_1802011_(MPI Inspection), Catcher sub 825_0040918_(MPI Inspection), Adjusting ring 825_1802003_(MPI Inspection), Rotor Coupling 825_1708009_(MPI Inspection), Shaft Coupling 825_1708009_(MPI Inspection), Shaft Coupling 825_1708003_(MPI Inspection)	8	To Be Created		D&M	<i>[Signature]</i>
6-Jul-23	Duri Base	08:00-17:00	Offset Housing 825_1801003_(MPI Inspection), Bearing Housing 825_1802001_(MPI Inspection), Stator Adapter 825_1801023_(MPI Inspection), Sleeve stab 12 1/8"HS_LILIN 2_(MPI Inspection), Bearing section 825_0140118_(MPI Inspection), String stab 10-3/8" HS - 900-2001-4-150650_(MPI Inspection)	8	To Be Created		D&M	<i>[Signature]</i>
7-Jul-23	Duri Base	08:00-17:00	Mud Motor End to end LL-210-1707007_(MPI Inspection)	8	To Be Created		D&M	<i>[Signature]</i>
TOTAL (hours)				40				

* If Applicable

[Signature]
 Satriadi Lamhot, Fero
 Personnel In Attendance

[Signature]
 Satriadi
 ISP Inspector

[Signature]
 Andy
 SLB Maintenance Technician

[Signature]
 Anson Kimmom
 SLB Maintenance Supervisor



PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET

Personnel In Attendance:

Mangera, Fero, Lamot

Period:

June-July 2023

Day Rate:

Per Diem Rate:

Customer:

PT. Sulthimberge Indonesia - D&M

Contact/ PO Non:

Rig / Well:

Duri Base

Date:

Our Ref:

Form No.:

Billing Date	Rig / Loc*	Time*	ACTIVITY (OVERTIME)	BILLING				
				Hours	WO Number	BORG	Segment	
8-Jul-23	Duri Base	08:00 - 21:00	Performed Full Body Inspection of 2 NMDC, Hole Opener, Crossover Bottleneck, Float Sub, String Stabilizer, SPSA, Gap Sub, Saver Sub, Crossover. Performed end to end inspection of Jar.	12	DURI-WCD-MOTOR-230717		D&M	
TOTAL (hours)				12				

* If Applicable

Mangera, Fero, Lamot
Personnel In Attendance

Mangera, Fero, Lamot
ISPI Inspector

Steph Andy
SLB Maintenance Technician

Anson R
SLB Maintenance Supervisor

**PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET**



Personnel In Attendance: Mangara, Faro, Lamhot
 Period: June-July 2023
 Day Rate: _____
 Per Diem Rate: _____

Customer: PT. Schlumberger Indonesia - DAM
 Contract PO Non: _____
 Rig / Well: _____
 Durl Base: _____

Date: _____
 Our Ref: _____
 Form No.: _____

Billing Date	Rig / Loc*	Time*	ACTIVITY	Hours	WO Number	BORG	Segment	BILLING	
								Company Representative Signature	
10-Jul-23	Durl Base	08.00 - 17.00	Performed Full Body Inspection of 2 String Stabilizer and Sleeve & End to end inspection of 3 Mud Motor.	8	DURI-WCD-MOTOR-230708		DAM	<i>Anson R</i>	
11-Jul-23	Durl Base	08.00 - 17.00	Performed Full Body Inspection of Telescope Collar and Crossover Bottleneck & End to end inspection of 3 Mud Motor	8	DURI-WCD-MOTOR-230708		DAM	<i>Anson R</i>	
12-Jul-23	Durl Base	08.00 - 17.00	Performed Full Body Inspection of 1 set Hole Opener & Inpection of SPSA, NMDC, Crossover After Repair	8	DURI-WCD-MOTOR-230708		DAM	<i>Anson R</i>	
13-Jul-23	Durl Base	08.00 - 17.00	Performed End to end inspection of 2 Mud Motor	8	DURI-WCD-MOTOR-230708		DAM	<i>Anson R</i>	
14-Jul-23	Durl Base	08.00 - 17.00	Performed Full Body Inspection Mud Motor 675 full set, String Stabilizer.	8	To Be Created		DAM	<i>Anson R</i>	
TOTAL (hours)				40					

* If Applicable

Mangara
 PT. INSPEKTINDO SINERGI PERSADA
 Mangara Lamhot, Faro
 Personnel In Attendance

Mangara
 PT. INSPEKTINDO SINERGI PERSADA
 Mangara Sianturi
 ISP Inspector

Andy
 SLB Maintenance Technician

Anson Rimmer
 SLB Maintenance Supervisor

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: Mangara, Fero, Lamhot
 Period: June-July 2023
 Day Rate: _____
 Per Diem Rate: _____

Customer: PT. Schlumberger Indonesia - DAM
 Contract/ PO No: _____
 Rig / Well: Duri Base

Date: _____
 Our Ref: _____
 Form No.: _____

Billing Date	Rig / Loc ^a	Time ^a	ACTIVITY (OVERTIME)	BILLING				
				Hours	WO Number	BORG	Segment	
10-Jul-23	Duri Base	17.00 - 20.00	Performed Full Body Inspection of 2 String Stabilizer and Sleeve & End to end inspection of 3 Mud Motor.	3 ✓	To Be Created		DAM	<i>Anson R</i>
11-Jul-23	Duri Base	17.00 - 19.00	Performed Full Body Inspection of Telescope Collar and Crossover Bottleneck & End to end inspection of 3 Mud Motor	2 ✓	To Be Created		DAM	<i>Anson R</i>
12-Jul-23	Duri Base	17.00 - 19.00	Performed Full Body Inspection of 1 set Hole Opener & Inspection of SPSA, NMDC, Crossover After Repair	2 ✓	To Be Created		DAM	<i>Anson R</i>
14-Jul-23	Duri Base	17.00 - 21.00	Performed Full Body Inspection Mud Motor 675 full set, String Stabilizer.	4 ✓	To Be Created		DAM	<i>Anson R</i>
15-Jul-23	Duri Base	17.00 - 23.00	Performed Inspection Mud Motor Power Section, Hole Opener 1 set.	6 ✓	To Be Created		DAM	<i>Anson R</i>
TOTAL (hours)				17 ✓				

^a If Applicable

Mangara

 Mangara Lamhot, Fero
 Personnel In Attendance

Mangara

 Mangara Stanhuri
 ISP Inspector

SLB
 SLB Maintenance Technician

Anson
 Anson Fimmon
 SLB Maintenance Supervisor

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: Mangara, Faro, Lamhot
 Period: June-July 2023
 Day Rate: _____
 Per Diem Rate: _____

Customer: PT. Schlumberger Indonesia - DAM
 Contract PO Non: _____
 Rig / Well: _____
 Durl Base: _____

Date: _____
 Our Ref: _____
 Form No.: _____

Billing Date	Rig / Loc*	Time*	ACTIVITY	Hours	WO Number	BORG	Segment	BILLING	
								Company Representative Signature	
10-Jul-23	Durl Base	08.00 - 17.00	Performed Full Body Inspection of 2 String Stabilizer and Sleeve & End to end inspection of 3 Mud Motor.	8	DURI-WCD-MOTOR-230708		DAM	<i>Anson R</i>	
11-Jul-23	Durl Base	08.00 - 17.00	Performed Full Body Inspection of Telescope Collar and Crossover Bottleneck & End to end inspection of 3 Mud Motor	8	DURI-WCD-MOTOR-230708		DAM	<i>Anson R</i>	
12-Jul-23	Durl Base	08.00 - 17.00	Performed Full Body Inspection of 1 set Hole Opener & Inpection of SPSA, NMDC, Crossover After Repair	8	DURI-WCD-MOTOR-230708		DAM	<i>Anson R</i>	
13-Jul-23	Durl Base	08.00 - 17.00	Performed End to end inspection of 2 Mud Motor	8	DURI-WCD-MOTOR-230708		DAM	<i>Anson R</i>	
14-Jul-23	Durl Base	08.00 - 17.00	Performed Full Body Inspection Mud Motor 675 full set, String Stabilizer.	8	To Be Created		DAM	<i>Anson R</i>	
TOTAL (hours)				40					

* If Applicable

Mangara
 PT. INSPEKTINDO SINERGI PERSADA
 Mangara Lamhot, Faro
 Personnel In Attendance

Mangara
 PT. INSPEKTINDO SINERGI PERSADA
 Mangara Sianturi
 ISP Inspector

Andy
 SLB Maintenance Technician

Anson Rimmer
 SLB Maintenance Supervisor

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: Mangara, Fero, Lamhot
 Period: June-July 2023
 Day Rate: _____
 Per Diem Rate: _____

Customer: PT. Schlumberger Indonesia - DAM
 Contract/ PO No: _____
 Rig / Well: Duri Base

Date: _____
 Our Ref: _____
 Form No.: _____

Billing Date	Rig / Loc ^a	Time ^a	ACTIVITY (OVERTIME)	BILLING				
				Hours	WO Number	BORG	Segment	
10-Jul-23	Duri Base	17.00 - 20.00	Performed Full Body Inspection of 2 String Stabilizer and Sleeve & End to end inspection of 3 Mud Motor.	3 ✓	To Be Created		DAM	<i>Anson R</i>
11-Jul-23	Duri Base	17.00 - 19.00	Performed Full Body Inspection of Telescope Collar and Crossover Bottleneck & End to end inspection of 3 Mud Motor	2 ✓	To Be Created		DAM	<i>Anson R</i>
12-Jul-23	Duri Base	17.00 - 19.00	Performed Full Body Inspection of 1 set Hole Opener & Inspection of SPSA, NMDC, Crossover After Repair	2 ✓	To Be Created		DAM	<i>Anson R</i>
14-Jul-23	Duri Base	17.00 - 21.00	Performed Full Body Inspection Mud Motor 675 full set, String Stabilizer.	4 ✓	To Be Created		DAM	<i>Anson R</i>
15-Jul-23	Duri Base	17.00 - 23.00	Performed Inspection Mud Motor Power Section, Hole Opener 1 set.	6 ✓	To Be Created		DAM	<i>Anson R</i>
TOTAL (hours)				17 ✓				

^a If Applicable

Mangara

 Mangara Lamhot, Fero
 Personnel In Attendance

Mangara

 Mangara Sianturi
 ISP Inspector

Anson
 SLB Maintenance Technician

Anson
 Anson Fimmon
 SLB Maintenance Supervisor

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:
 Period:
 Day Rate:
 Per Diem Rate :

Customer:
 Contract/ PO Non:
 Rig / Well:

Date :
 Our Ref:
 Form No. :

Billing Date	Rig / Loc*	Time*	ACTIVITY (Regular)	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
17-Jul-23	Duri Base	08.00 - 17.00	Performed Inspection Jar, Telescope Collar, NMDC, 2 Float Sub, Crossover Bottleneck, String Stabilizer	8	To Be Created		D&M	
18-Jul-23	Duri Base	08.00 - 17.00	Performed Inspection 2 NMDC, 4 String Stabilizer, SPSA, Ponny Collar, Mud motor (end to end), Mud motor Power Section, Crossover Bottleneck	8	To Be Created		D&M	
20-Jul-23	Duri Base	08.00 - 17.00	Performed Inspection NMDC, 2 Pony Collar, Crossover bottleneck, 2 Float sub, Rotor, String stabilizer, Mud motor (end to end), Jar.	8	To Be Created		D&M	
TOTAL (hours)				24				

* If Applicable

Mangara Lamhot Fero
 Personnel In Attendance

Mangara Sianturi
 ISP Inspector

 SLB Maintenance Technician

 SLB Maintenance Supervisor

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:
 Period:
 Day Rate:
 Per Diem Rate :

Customer:
 Contract/ PO Non:
 Rig / Well:

Date :
 Our Ref:
 Form No. :

Billing Date	Rig / Loc*	Time*	ACTIVITY (Over Time)	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
17-Jul-23	Duri Base	17.00 - 19.00	Performed Inspection Jar, Telescope Collar, NMDC, 2 Float Sub, Crossover Bottleneck, String Stabilizer	2	To Be Created		D&M	
18-Jul-23	Duri Base	17.00 - 21.00	Performed Inspection 2 NMDC, 4 String Stabilizer, SPSA, Pony Collar, Mud motor (end to end), Mud motor Power Section, Crossover Bottleneck	4	To Be Created		D&M	
19-Jul-23	Duri Base	08.00 - 21.00	Performed Inspection Mud motor (end to end), NMDC, Jar, SPSA, Mud motor Power Section	12	To Be Created		D&M	
20-Jul-23	Duri Base	17.00 - 22.00	Performed Inspection NMDC, 2 Pony Collar, Crossover bottleneck, 2 Float sub, Rotor, String stabilizer, Mud motor (end to end), Jar.	5	To Be Created		D&M	
TOTAL (hours)				23				

* If Applicable



Mangara Lamhot Fero
Personnel In Attendance



Mangara Sianturi
ISP Inspector

SLB Maintenance Technician

SLB Maintenance Supervisor

PT. INSPEKTINDO SINERGI PERSADA SERVICES TIME SHEET



Personnel In Attendance: Mangara, Fero, Lamhot

Period: 15-Jul-23

Day Rate:

Per Diem Rate :

Customer: SLB - CPS

Contract/ PO Non: 230712 - CPL

Rig / Well: SLB DURI

Date : 16-Jul-23

Our Ref:

No	Day & Date	Rig / Loc*	Time*	ACTIVITY	BORG	BILLING		
						Day	Mob/ Demob (USD)	Per diem (Day)
1	15/07/2023	DURI	08.00 - 17.00	Performed Full Body Inspection and Connection of Completion Tools	-	1		
Note: Assistant: * If Applicable						TOTAL (Days)	1	
						TOTAL (USD)		
						GRAND TOTAL		

Consumable Material Usage				
No	Date & Day	Material Usage	Quantity	Remark
1	15/07/2023	Paint remover	1	
		WCP	2	
		7 HF	2	

Mangara Sianturi
 Personnel In Attendance

Contractor Representative

Rig Representative

The Company Representative

