## PT. INSPEKTINDO SINERGI PERSADA SERVICES TIME SHEET



Date :

Our Ref:

 Pambudhi Kristyanto
 Customer:
 Pertamina Hulu Kalimantan Timur

 Contract/ PO Non:
 Rig / Well:
 AWB. Bayu Constructor

BILLING No Day & Date Rig / Loc\* ACTIVITY Time\* Mob/ Demob Per diem Day (USD) (Day) Mobilization to AWB Bavu Constructor, Inspection/audit performance Generator (5 units), Compressor (2 units), 06.00-18.00 Inspection has conducted for Review Document, Tagging Verification, Visual Inspection, and Verification Function 1 10-Jan-23 1 Test Inspection/audit performance of Pedestal Crane, Jumping rope, Gang way, Service Company CCU .Inspection has conducted for Review Document, Tagging Verification, Visual Inspection, and Verification Function Test W/idle 06.00-18.00 RPM (800 RPM) for 90 minutes, verification function test W/Max RPM (1600 RPM) for 10 minutes, verification test 2 11-Jan-23 1 swing, boom up & down, hoist up & down, verification test safety device (anti two block main & aux, load indicator & brake system) emergency shut down test Inspection/audit performance of Anchor Winch Unit, AWB Lifting Gear. Inspection has conducted for Review 3 12-Jan-23 06.00-18.00 1 Document, Tagging Verification, Visual Inspection. Continue Demobilization to Balikpapan TOTAL (Days) 3 TOTAL (USD)

\* If Applicable

Consumable Material Usage				
No	Date & Day	Material Usage	Quantity	Remark

Personnel In Attendance:

Period:

Day Rate: Per Diem Rate :

Nana Supriyatna

GRAND TOTAL

Ardi Septiawan Engineer QAQC DWLI Zona 10/Eng. Drilling The Company Representative

Pambudhi Kristyanto Personnel In Attendance

Contractor Representative

Rig Representative

ISP-F10-HR-02