

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Persohn / In Attendance:

1.Chasan, 2. Albert, 3. Levi, 4. Iskandar, 5. Swargi, 6 Andik K. 7. Reza K.

Customer:

Pertamina EP Zona 10 Bunyu, Tarakan dan Sembakung Field

Date :

20-Oct-22

Period:

October 2022

Contract/ PO Non:

4710000000

Our Ref:

Service Date:

21 Sept - 20 October 2022

Rig / Well:

Bunyu Well

Billing Date	Rig / Loc ^a	Time ^a	ACTIVITY	Material Origin (PO No. / Well Name)	BILLING	
					Day	Mob & Demob (Material/Peralatan)
21-Sep-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 13-3/8" OD, 54.5 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 12.456".	RO No: 4300072035	1	1
22-Sep-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 13-3/8" OD, 54.5 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 12.456".	RO No: 4300072035	1	1
23-Sep-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 13-3/8" OD, 54.5 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 12.456".	RO No: 4300072035	1	1
24-Sep-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 7" OD, 26 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 6.151".	RO No: 4300071106	1	1
25-Sep-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 7" OD, 26 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 6.151".	RO No: 4300071106	1	1
26-Sep-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 7" OD, 26 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 6.151".	RO No: 4300071106	1	1
27-Sep-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
28-Sep-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
29-Sep-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 7" OD, 26 PPF, N-80Q, BUTTRESS Conn, Length R-2, API Drift 6.151".	RO No: 4300054933	1	1
30-Sep-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
1-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
2-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
3-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
4-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
5-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 9 5/8" OD, 40 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 8.679".	RO No: 4300071106	1	1
6-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 13-3/8" OD, 54.5 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 12.456".	RO No: 4300072035	1	1
7-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 13-3/8" OD, 54.5 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 12.456".	RO No: 4300072035	1	1
8-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 13-3/8" OD, 54.5 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 12.456".	RO No: 4300072035	1	1
9-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 13-3/8" OD, 54.5 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 12.456".	RO No: 4300072035	1	1

**PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET**



Personnel In Attendance:

1. Chasan, 2. Albert, 3. Levi, 4. Iskandar, 5. Swargi, 6. Andik K. 7. Reza K.

Customer: Pertamina EP Zona 10 Bunyu, Tarakan dan Sembakung Field

Date: 20-Oct-22

Period: October 2022

Contract/ PO Non: 4710000000

Our Ref:

Service Date: 21 Sept - 20 October 2022

Rig / Well: Bunyu Well

Billing Date	Rig / Loc*	Time*	ACTIVITY	Material Origin (PO No. / Well Name)	BILLING	
					Day	Mob & Demob (Material/Peralatan)
10-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 13-3/8" OD, 54.5 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 12.456"	RO No: 4300072035	1	1
11-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 13-3/8" OD, 54.5 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 12.456"	RO No: 4300072035	1	1
12-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 13-3/8" OD, 54.5 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 12.456"	RO No: 4300072035	1	1
13-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 13-3/8" OD, 54.5 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 12.456"	RO No: 4300072035	1	1
14-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 13-3/8" OD, 54.5 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 12.456"	RO No: 4300072035	1	1
15-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 13-3/8" OD, 54.5 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 12.456"	RO No: 4300072035	1	1
16-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 13-3/8" OD, 54.5 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 12.456"	RO No: 4300072035	1	1
17-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 13-3/8" OD, 54.5 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 12.456"	RO No: 4300072035	1	1
18-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 13-3/8" OD, 54.5 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 12.456"	RO No: 4300072035	1	1
19-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 13-3/8" OD, 54.5 PPF, K-55, BUTTRESS Conn, Length R-3, API Drift 12.456"	RO No: 4300072035	1	1
20-Oct-22	Bunyu Field	07.00 - 16.00	Pipe Yard Management & Inspection of Casing 7" OD, 26 PPF, N-80Q, BUTTRESS Conn, Length R-3, API Drift 6.151"	RO No: 430007173	1	1
TOTAL (Days)					30	30

Musthopa
Chasan Musthopa / Idham
Personnel In Attendance

Field Site Representative

Ardi Septiawan
The Company Representative

