

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance: **Yulius k**  
**Reza Achmad**

Customer: **PERTAMINA HULU**  
**MAHAKAM**

Service Date: **14-Sep-2021**

Periode : **Sep-Oct**

CRO No.:

Rig/Well : **PECIKO**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			8-Sep	9-Sep	10-Sep	11-Sep	12-Sep	13-Sep	14-Sep	
1	Pedestal Crane		IP		IP	1				1
2	Cargo Carrying Unit		1							1
3	Wire Rope Sling 3-leg or 4-legs				1					1
4	Shackle				4					4
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
<b>Equipment Rental</b>										
1	Water bag 3 tonnes	unit-day								
2	Water bag 12 tonnes	unit-day								
3	Load Cell 5 tonnes	unit-day								
4	Load Cell 30 tonnes	unit-day								
5	Wire rope tester	unit-day				1				1
<b>PROVISION</b>										
7	Land Transportation	unit-day	1		1	1				3
8	Meal allowance	man-day	2		2	2				6

**Yulius k**  
Personnel In Attendance

**IWAN S / ABU KHOIRI**  
Approved by PHM sites INS SPV