

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: M. Arya Wachid A. - Thoro S. - Mahfud
 Period: June - July 2023
 Day Rate: -
 Per Diem Rate: -

Customer: SLB - Well Construction Drilling
 Contractor/ PO Non: -
 Rig/ Well: Cikarang Integrated Base

Date: -
 Out Ref: -
 Form No: -

Billing Date	Rig/ Loc*	Time*	ACTIVITY (TOOL NAME_SNH_CATEGORY (Cleaning/Inspection/Ex Machine Shop) Ex: TeleScope Collar_G3759_Ex Machine Shop	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Respresentative Signature
03/07/2023	CIB	08.30 - 17.30	KM8 HQ - V75307, UDM - 95251239-036 & Sleeve - 4760 for SAKA (Inspection); Rhino Body 9150598-003 & Rhino Body 9459916-002 or 40448HA Prepare for Mubadala/Harbour (Cleaning)	8	WCD_BDT_AFTER RECHROOM (28/06/2023) & MI-ST-071123-WCMD8-PEP-EWO-001 (11-Jul-2023)	-	WCD	
04/07/2023	CIB	08.30 - 17.30	WCMD8 B2011107A, WCMD8 B2006533A, BBC8 B2004948, BBC8 B2008214, 2 set of WCMD Part (16 ea), Sleeve Catcher 16862-AA & Sleeve Catcher 4941 Witnessed by Mubadala/Harbour (Inspection); 8.5 PDC Bit JV2473 Pertamina (Inspection)	8	WCD_BDT_BIT 8.5 & 17.5 (15-Jul-2023) & MI-ST-071423-WCMD8-MUBADALA-HARBOUR (11-Jul-2023)	-	WCD	
05/07/2023	CIB	08.30 - 17.30	12.25 PDC Bit JV6424 at PT IMECO & PC OSCA41756 (Inspection); BBC7 B2000720A, B. Magno B2003582, CCT B2005035A, 26 inch RC Bit - RP8296 & RP8350 Witnessed by Mubadala/Harbour (Inspection)	8	WCD_BDT_BIT 12.174-JV6424 (07/07/2023), WCD_BDT_HQ650_PC_OSCA41756 (05/07/2023) & MI-ST-071023-WBCO-MUBADALA-HARBOUR (15-Jul-2023)	-	WCD	
06/07/2023	CIB	08.30 - 17.30	26 inch RC Bit - RP8296 & RP8350 & 1 set of Rhino Reamer XC - 40448HA Witnessed by Mubadala/Harbour (Inspection)	8	WCD_BDT_RHINO XC 11625-40448HA (13-Jul-2023)	-	WCD	
07/07/2023	CIB	08.30 - 17.30	1 set of Rhino Reamer XC - 40448HA Witnessed by Mubadala/Harbour (Inspection); UFJ - AJ21204 & LFJ - OSCA339833 (Inspection)	8	WCD_BDT_RHINO XC 11625-40448HA (13-Jul-2023) & WCD_BDT_AFTER REPAIR (06-Jul-2023)	-	WCD	
TOTAL (hours)								

*If Applicable

Thoro & Mahfud
ISP Personnel in Attendance

ISP Inspector

SLB Maintenance Technician

SLB Maintenance Supervisor

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: M. Arya Wachid A. - Thoro S. - Mahfud
 Period: June - July 2023
 Day Rate: -
 Per Diem Rate: -

Customer: SLB - Well Construction Drilling
 Contractor/ PO Non: -
 Rig/ Well: Cikarang Integrated Base

Date: -
 Out Ref: -
 Form No: -

Billing Date	Rig/ Loc*	Time*	ACTIVITY (TOOL NAME _SN#_ CATEGORY (Cleaning/Inspection/Ex Machine Shop) Ex: TeleScope Collar_G3759_ Ex Machine Shop	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
10/07/2023	CIB	08.30 - 17.30	Top Sub - 86174H, Bottom Sub - N27778A, Cam Sub - 43515K, Piston - 9319940-006 & Cutter Block - 9615753-003 Witnessed by Mubadala/Harbour (Inspection); HQ800 - 33798H & HQ800 - 33796H Witnessed by Pertamina (Inspection)	8	WCD_BDT_RHINO XC 11625-40448HA (13-Jul-2023) & WCD_BDT_JAR (14-Jul-2023)	-	WCD	
11/07/2023	CIB	08.30 - 17.30	Rhino Body - 9150598-003 Witnessed by Mubadala/Harbour (Inspection); WCMD - B2000729A & B2004908A, BBC - B2008210A & B2002300A & HJ650 - OSC106906AWitnessed by Pertamina (Inspection)	8	MI-ST-071123-WCMD8-PEP-EWO-001 (11-Jul-2023) & WCD_BDT_JAR (14-Jul-2023)	-	WCD	
12/07/2023	CIB	08.30 - 17.30	Lower Mandrel Sleeve AJ96299, Lower Mandrel Seal AJ31126, Lower Mandrel AJ35918, 8.5 RC Bit - RPS355, 10.625 PDC Bit - C/F7154, 12.25 RC Bit - RP8566 & 6 RC Bit - RPS878, 2 ea Bit Breaker, Cover Spring, Drive Ring Retainer, Cutter Block - 9641056-003, Spring & Stop Ring - 8245267-003 Witnessed by Mubadala/Harbour (Inspection)	8	WCD_BDT_BIT FOR MUBADALA (17-Jul-2023), WCD_BDT_LOWER MANDREL RHINO XC 11625 (17-Jul-2023) & WCD_BDT_RHINO XC 11625 - 9150598-003 (17-Jul-2023) & WCD_BDT_RHINO XC 11625 - 9150598-003 (17-Jul-2023)	-	WCD	
13/07/2023	CIB	08.30 - 17.30	HQ650 - 33797H & HQ650 - 64375H Witnessed by Pertamina & stucked drift (Inspection); 1 set of HJ700 - 93556H & part of RR XC - 9150598-003 Prepare for Mubadala/Harbour (Cleaning)	8	WCD_BDT_HQ800 (13-Jul-2023) & WCD_BDT_HJ700-93556H (14-Jul-2023)	-	WCD	
14/07/2023	CIB	08.30 - 17.30	1 set of HJ700 - 93556H & part of RR XC - 9150598-003 Witnessed by Mubadala/Harbour (Inspection)	8	WCD_BDT_HJ700-93556H (14-Jul-2023) & WCD_BDT_RHINO XC 11625 - 9150598-003 (17-Jul-2023)	-	WCD	
TOTAL (hours)								

*If Applicable

Thoro & Mahfud
ISP Personnel in Attendance

Wachid
ISP Inspector

Final
SLB Maintenance Technician

Yael A
SLB Maintenance Supervisor

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: M. Arya Wachid A. - Thoro S. - Mahfud
 Period: June - July 2023
 Day Rate: -
 Per Diem Rate: -

Customer: SLB - Well Construction Drilling
 Contractor/ PO Non: -
 Rig/ Well: Cikarang Integrated Base

Date: -
 Out Ref: -
 Form No: -

Billing Date	Rig/ Loc*	Time*	ACTIVITY (TOOL NAME_S#_CATEGORY (Cleaning/Inspection/Ex Machine Shop) Ex: TeleScope Collar_G3759_Ex Machine Shop	BILLING				
				Hour/s	WO Number	BORG	Segment	Company Representative Signature
26/06/2023	CIB	08.30 - 17.30	8.5 X5616 - JP3831, 12.25 SD1519MHBPX - JP8906, 12.25 SD1519MHBPX - JN7210 & 17.5 MD1519LHBPX - JK8282 at PT IMECO (Inspection)	8	WCD_BDT_BIT * (27/06/2023)	-	WCD	
27/06/2023	CIB	08.30 - 17.30	6 1/2" Kelly Mandrel - U94149 (Inspection); HJ475-54244H & HJ475-81862H (Cleaning)	8	WCD_BDT_AFTER REPAIR (26/06/2023), WCD_BDT_HJ475-54244H (27/06/2023) & WCD_BDT_HJ475-81862H (27/06/2023)	-	WCD	
28/06/2023	CIB	08.30 - 17.30	HJ475-54244H & HJ475-81862H - Witnessed by Medco (Inspection);	8	WCD_BDT_HJ475-54244H (27/06/2023) & WCD_BDT_HJ475-81862H (27/06/2023)	-	WCD	
30/06/2023	CIB	08.30 - 17.30	LS 475 - 9153739-002 (Inspection); WP - MI2190 & Parts, XO - KSU165-16856-0101, XO / Extension - GPS 598279-4, Valve Housing - 19A & 19B, Stand of Sleeve - 19C, Stand of Ring - 19D & Cup Screen - 19E Witnessed by SAKA (Inspection)	8	WCD_BDT_AFTER REPAIR (26/06/2023), MI-ST-071023-WBCO-MUBADALA-HARBOUR (16-Jul-2023) & MI-ST-052623-AR-SAKA (21/06/2023)	-	WCD	
TOTAL (hours)								

*If Applicable

Thoro & Mahfud
ISP Personnel in Attendance

Wachid
ISP Inspector

Fairul
SLB Maintenance Technician

YCC1-A
SLB Maintenance Supervisor