

**PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET**



Personnel In Attendance: Agus Mulyono, Dede Kurniawan, Riski M. Taslim, Arif Syafuddin A, Dedy Heriyanto S, M. Razif

Period: August 2022

Day Rate:

Per Diem Rate:

Customer: PERTAMINA HULU KALIMANTAN TIMUR

Contract/ PO No: KTAD-DC100S

Rig / Well: RKS SHOREBASE - PENDINGIN

Date: 20 August 2022

Our Ref:

Form No.:

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING		
				Day	Mob/ Demob (USD)	Per diem (Day)
21-Jul-22	Pendingin Shore Base	08.00 - 17.00	Re-Inspection and Maintenance Regulation of Tubing 3.500" OD, 9.20 PPF, L80, TSH Blue Conn, Length R2 - 72 Joints MM-560	1		
22-Jul-22	Pendingin Shore Base	08.00 - 17.00	Re-Inspection and Maintenance Regulation of Tubing 3.500" OD, 9.20 PPF, L80, TSH Blue Conn, Length R2 - 72 Joints MM-560	1		
23-Jul-22	Pendingin Shore Base	06.00 - 17.00	Re-Inspection and Maintenance Regulation of Tubing 3.500" OD, 9.20 PPF, L80, TSH Blue Conn, Length R2 - 96 Joints MM-560	1		
24-Jul-22	Pendingin Shore Base	06.00 - 17.00	Re-Inspection and Maintenance Regulation of Tubing 3.500" OD, 9.20 PPF, L80, TSH Blue Conn, Length R2 - 72 Joints MM-560	1		
25-Jul-22	Pendingin Shore Base	08.00 - 17.00	Re-Inspection and Maintenance Regulation of Tubing 3.500" OD, 9.20 PPF, L80, TSH Blue Conn, Length R2 - 72 Joints MM-560	1		
26-Jul-22	Pendingin Shore Base	08.00 - 17.00	Re-Inspection and Maintenance Regulation of Tubing 3.500" OD, 9.20 PPF, L80, TSH Blue Conn, Length R2 - 72 Joints MM-560	1		
27-Jul-22	Pendingin Shore Base	08.00 - 17.00	Re-Inspection and Maintenance Regulation of Tubing 3.500" OD, 9.20 PPF, L80, TSH Blue Conn, Length R2 - 96 Joints MM-560	1		
28-Jul-22	Pendingin Shore Base	08.00 - 17.00	Re-Inspection and Maintenance Regulation of Tubing 3.500" OD, 9.20 PPF, L80, TSH Blue Conn, Length R2 - 24 Joints MM-560 Inspection and Maintenance Back Load of Casing 7.000" OD, 29.00 PPF, TSH Blue Conn, Length R3 - 30 Joints MM-494, 495, 566, 684, 685, 606 & 517 Inspection and Maintenance Back Load of Crossover 9.625" OD, 53.50 PPF, TSH Blue X Buttress Conn, Length 4 Ft - 1 Joint MM-576	1		
29-Jul-22	Pendingin Shore Base	08.00 - 17.00	Re-Inspection and Maintenance Regulation of Tubing 3.500" OD, 9.20 PPF, L80, TSH Blue Conn, Length R2 - 72 Joints MM-560	1		
30-Jul-22	Pendingin Shore Base	07.00 - 17.00	Re-Inspection and Maintenance Regulation of Tubing 3.500" OD, 9.20 PPF, L80, TSH Blue Conn, Length R2 - 120 Joints MM-560	1		
31-Jul-22	Pendingin Shore Base	07.00 - 17.00	Inspection and Maintenance Back Load of Casing 9.625" OD, 53.50 PPF, P110, TSH Blue Conn, Length R3 - 21 Joints MM-597, 611, 436 & 686 Inspection and Maintenance Back Load of Pup Joint 7.000" OD, 29.00 PPF, TSH Blue Conn, Various Length - 6 Joints MM-495 & 470	1		
1-Aug-22	Pendingin Shore Base	08.00 - 17.00	Inspection and Maintenance Back Load of Casing 9.625" OD, 53.50 PPF, P110, TSH Blue Conn, Length R3 - 32 Joints MM-436 & 437	1		
2-Aug-22	Pendingin Shore Base	08.00 - 17.00	Maintenance Record Tools & General House Keeping	1		
3-Aug-22	Pendingin Shore Base	08.00 - 17.00	Inspection and Maintenance Back Load of Casing 7.000" OD, 29.00 PPF, L80, TSH Blue Conn, Length R3 - 35 Joints MM-395 & 631	1		
4-Aug-22	Pendingin Shore Base	08.00 - 17.00	Inspection and Maintenance Back Load of Tubing 3.500" OD, 9.20 PPF, L80, TSH Blue Conn, Length R2 - 69 Joints MM-205 & 568	1		
5-Aug-22	Pendingin Shore Base	08.00 - 17.00	Inspection and Maintenance Back Load of Tubing 3.500" OD, 9.20 PPF, L80, TSH Blue Conn, Length R2 - 79 Joints MM-205 & 568	1		
6-Aug-22	Pendingin Shore Base	08.00 - 17.00	Inspection and Maintenance Back Load of Tubing 3.500" OD, 9.20 PPF, L80, TSH Blue Conn, Length R2 - 84 Joints MM-205, 461 & 568	1		
7-Aug-22	Pendingin Shore Base	07.00 - 17.00	Inspection and Maintenance Back Load of Tubing 3.500" OD, 9.20 PPF, L80, TSH Blue Conn, Length R2 - 24 Joints MM-461 Re-Inspection and Maintenance Regulation of Tubing 3.500" OD, 9.20 PPF, L-80, TSH Blue Conn, Length R2 - 73 Joints MM-568	1		
8-Aug-22	Pendingin Shore Base	08.00 - 17.00	Re-Inspection and Maintenance Regulation of Tubing 3.500" OD, 9.20 PPF, L80, TSH Blue Conn, Length R2 - 72 Joints MM-568	1		
9-Aug-22	Pendingin Shore Base	08.00 - 17.00	Re-Inspection and Maintenance Regulation of Tubing 3.500" OD, 9.20 PPF, L80, TSH Blue Conn, Length R2 - 72 Joints MM-567	1		
10-Aug-22	Pendingin Shore Base	08.00 - 17.00	Re-Inspection and Maintenance Regulation of Tubing 3.500" OD, 9.20 PPF, L80, TSH Blue Conn, Length R2 - 72 Joints MM-567	1		
11-Aug-22	Pendingin Shore Base	08.00 - 17.00	Re-Inspection and Maintenance Regulation of Tubing 3.500" OD, 9.20 PPF, L80, TSH Blue Conn, Length R2 - 66 Joints MM-567 & 568	1		
12-Aug-22	Pendingin Shore Base	08.00 - 17.00	Re-Inspection and Maintenance Regulation of Tubing 3.500" OD, 9.20 PPF, L80, TSH Blue Conn, Length R2 - 30 Joints MM-568 Inspection and Maintenance Back Load of Pup Joint 3.500" OD, 9.20 PPF, L-80, TSH Blue Conn, Various Length - 17 Joints MM-492 Inspection and Maintenance Back Load of Pup Joint 3.500" OD, 9.20 PPF, L-80 13CR, TSH Blue Conn, Various Length - 13 Joints MM-493 & 645	1		
13-Aug-22	Pendingin Shore Base	07.00 - 17.00	Re-Inspection and Maintenance Regulation of Tubing 3.500" OD, 9.20 PPF, L80, TSH Blue Conn, Length R2 - 96 Joints MM-560	1		
14-Aug-22	Pendingin Shore Base	08.00 - 17.00	Re-Inspection and Maintenance Regulation of Tubing 3.500" OD, 9.20 PPF, L80, TSH Blue Conn, Length R2 - 96 Joints MM-560	1		
15-Aug-22	Pendingin Shore Base	08.00 - 17.00	Re-Inspection and Maintenance Regulation of Tubing 3.500" OD, 9.20 PPF, L80, TSH Blue Conn, Length R2 - 81 Joints MM-560	1		
16-Aug-22	Pendingin Shore Base	08.00 - 17.00	Inspection and Maintenance Back Load of Tubing 3.500" OD, 9.20 PPF, L80 13CR, TSH Blue Conn, Length R2 - 42 Joints MM-579 Inspection and Maintenance Back Load of Tubing 3.500" OD, 9.20 PPF, TN95 13CR, TSH Blue Conn, Length R3 - 4 Joints MM-077 Inspection and Maintenance Back Load of Tubing 3.500" OD, 9.20 PPF, L80, TSH Blue Conn, Length R2 - 4 Joints MM-205 & 280 Inspection and Maintenance Back Load of Casing 7.000" OD, 29.00 PPF, N80-Q, TSH Blue Conn, Length R3 - 2 Joints MM-556 & 592	1		
17-Aug-22	Pendingin Shore Base	08.00 - 17.00	Re-Inspection and Maintenance Regulation of Tubing 3.500" OD, 9.20 PPF, L80, TSH Blue Conn, Length R2 - 96 Joints MM-560	1		
18-Aug-22	Pendingin Shore Base	08.00 - 17.00	Re-Inspection and Maintenance Regulation of Tubing 3.500" OD, 9.20 PPF, L80, TSH Blue Conn, Length R2 - 82 Joints MM-560	1		
19-Aug-22	Pendingin Shore Base	08.00 - 17.00	Re-Inspection and Maintenance Regulation of Tubing 3.500" OD, 9.20 PPF, L80, TSH Blue Conn, Length R2 - 83 Joints MM-560	1		
20-Aug-22	Pendingin Shore Base	08.00 - 17.00	Re-Inspection and Maintenance Regulation of Tubing 3.500" OD, 9.20 PPF, L80, TSH Blue Conn, Length R2 - 96 Joints MM-560	1		
				TOTAL (Days)	31	
				TOTAL (USD)		
				GRAND TOTAL		

* If Applicable

Agus Mulyono
20/08/2022
PT INSPEKTINDO SINERGI PERSADA
Personnel In Attendance

Contractor Representative

Rig Representative

SURYA MANDANI
The Company Representative
20 AUG 2022