

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: **Pambudhi Kristyanto**
Agus salim asbar

Customer: **PERTAMINA HULU**
MAHAKAM


Service Date: **29-Jun-2021**


Periode : **Jun - Jul**

CRO No.:

Rig/Well : **NPU**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			23-Jun	24-Jun	25-Jun	26-Jun	27-Jun	28-Jun	29-Jun	
1	Beam Trolley		4	2		1	3			10
2	Gantry		1	1						2
3	Runway Beam		11	7	3	8	7			36
4	Chain Block		2	1			1		1	5
5	Slewing Jib Davit		1	3		4				8
6	Pad Eye		1	7	12	2	8			30
7	Shackle							23	8	31
8	Hydraulic Ram & Jack							1		1
9	Eye Bolt								12	12
10	Polyester Sling								11	11
11	Wire Rope Sling 3-leg or 4-legs								1	1
12										
13										
14										
15										
Equipment Rental										
1	Water bag 3 tonnes	unit-day								
2	Water bag 12 tonnes	unit-day								
3	Load Cell 5 tonnes	unit-day								
4	Load Cell 30 tonnes	unit-day								
5	Wire rope tester	unit-day								
PROVISION										
7	Land Transportation	unit-day								
8	Meal allowance	man-day								


Pambudhi Kristyanto
Personnel In Attendance

Bambang YUDHONO
29 JUN 2021

Approved by PHM sites INS SPV