

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance: **1. Erwin Nugraha**  
**2. Ahmad Fuad Kaltimuja**

Customer: **PERTAMINA HULU MAHAKAM**

Service Date: **07 October 2020**

Periode: **September 2020**

CRO No.: **0**

Rig/Well: **HANDIL BASE**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			1-Oct	2-Oct	3-Oct	4-Oct	5-Oct	6-Oct	7-Oct	
1	POLYESTER SLING	HCA	32	12						44
2	CARGO CARRYING UNIT	HCA		3	4					7
3	WIRE ROPE SLING 4 LEG	HCA			4					4
4	GANTRY	HCA							5	5
5										0
7										0
8										0
9										0
11										0
12										0
13										0
14										0
15										0
16										0
17										0
18										0
<b>Equipment Rental</b>										
1	Water bag 3 tonnes	unit-day	0	0	0	0	0	0	0	0
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0	0	0
3	Load Cell 5 tonnes	unit-day	0	0	0	0	0	0	1	1
4	Load Cell 30 tonnes	unit-day	0	0	0	0	0	0	0	0
5	Wire rope tester	unit-day	0	0	0	0	0	0	0	0
<b>PROVISION</b>										
7	Land Transportation	unit-day	1	1	1	0	0	0	1	4
8	Meal allowance	man-day	2	2	2	0	0	0	2	8

**Erwin Nugraha**  
Personnel In Attendance

*11/20 FOR*  
  
**Nanang As'ary**  
Approved by PHM sites INS SPV

17