

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance: **1. Suhardi Maricen**  
**2. Ermawan Eka S**

Customer: **PERTAMINA HULU MAHAKAM**

Service Date: **July 20, 2020**

Periode : **July-2020**

CRO No.: **4200139209**

Rig/Well : **SPU BASE**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			14-Jul	15-Jul	16-Jul	17-Jul	18-Jul	19-Jul	20-Jul	
1	Pedestal Crane	SPU		1		1				2
2	Cargo Carrying Unit Including Lifting Set	SPU	1	1	1		1		3	7
3	Cargo Carrying Unit	SPU	1	2	1	1	2	1	4	12
4	Wire Rope Sling - 1 legs	SPU				1				1
5	Wire Rope Sling - 2 legs	SPU		1	2		1		2	6
6	Wire Rope Sling - 4 legs	SPU					1		2	3
7	Shackle	SPU	1	2	4		6		12	25
8	Other Below The Hook Lifting Devices	SPU	1							1
9	Beam Clamp	SPU						1		1
11	Runway Beam	SPU						2		2
12	Beam Trolley	SPU						1		1
13										0
14										0
15										0
16										0
17										0
<b>Equipment Rental</b>										
1	Water bag 3 tonnes	unit-day	0	0	0	0	0	0	0	0
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0	0	0
3	Load Cell 5 tonnes	unit-day	0	0	0	0	0	0	0	0
4	Load Cell 30 tonnes	unit-day	0	0	0	0	0	0	0	0
5	Wire rope tester	unit-day	1	1	1	1	1	1	1	7
<b>PROVISION</b>										
7	Land Transportation	unit-day	0	0	0	0	0	0	0	0
8	Meal allowance	man-day	0	0	0	0	0	0	0	0

**Suhardi Maricen**  
Personnel In Attendance

**Gunawan / A.Isyudanto**  
Approved by PHM sites INS SPV