



**PT. INSPEKTINDO SINERGI PERSADA**  
**DAILY INSPECTION REPORT SUMMARY**



Name & address of employer for whom the thorough examination was made:					Address of premises at which the examination was made:					PO No. :			
PT. PATRA DRILLING CONTRACTOR Balikpapan					PHM Handil Bravo 1 Jetty					RFI No. :			
No	Description	ID number	Manufacture	SWL/Payload	Size/Dim	Examination Type				Date of Inspection	Inspection Result	Performer	Remarks
						CoC	Visual	NDT	Load Testing				
1	Dry Container. Tare: 2200 kg. MGM: 9700 kg.	TRUI 2319370	NIGBO PASIFIC CONTAINER CO LTD	7500 KG	6040 x 2440 x 2590 mm (LxWxH)	-	√	-	-	11/6/2021	Accepted	Pambudhi Kristyanto	Need to Maintenance of ISO CORNER Section and Need to put Information Remark of Tare, Payload and MGM.
2	4 legged wire rope sling	TBM/C/20/0071	TALIMAS	27.6 ton 0-45 deg	32 mm x 5 meters	-	√	-	-	11/6/2021	Accepted	Pambudhi Kristyanto	
3	Safety Pin Bow Shackle	JLD 017	Crosby	13.5 ton	1-3/8 inch	-	√	-	-	11/6/2021	Accepted	Pambudhi Kristyanto	
4	Safety Pin Bow Shackle	JLD 018	Crosby	13.5 ton	1-3/8 inch	-	√	-	-	11/6/2021	Accepted	Pambudhi Kristyanto	
5	Safety Pin Bow Shackle	JLD 019	Crosby	13.5 ton	1-3/8 inch	-	√	-	-	11/6/2021	Accepted	Pambudhi Kristyanto	
6	Safety Pin Bow Shackle	JLD 020	Crosby	13.5 ton	1-3/8 inch	-	√	-	-	11/6/2021	Accepted	Pambudhi Kristyanto	
7	Dry Container. Tare: 1750 kg. MGM: 5150 kg.	TRUI 4701531	PT. JAVA PASIFIC	3400 KG	3000 x 2440 x 2580 mm (LxWxH)	-	√	√	-	11/6/2021	Accepted	Pambudhi Kristyanto	Need to Maintenance of ISO CORNER Section
8	4 legged wire rope sling	TBM/C/20/0072	TALIMAS	15.5 ton 0-45 deg	24 mm x 4 meters	-	√	-	-	11/6/2021	Accepted	Pambudhi Kristyanto	
9	Safety Pin Bow Shackle	JLD 009	Crosby	6.5 ton	7/8 inch	-	√	-	-	11/6/2021	Accepted	Pambudhi Kristyanto	
10	Safety Pin Bow Shackle	JLD 010	Crosby	6.5 ton	7/8 inch	-	√	-	-	11/6/2021	Accepted	Pambudhi Kristyanto	
11	Safety Pin Bow Shackle	JLD 011	Crosby	6.5 ton	7/8 inch	-	√	-	-	11/6/2021	Accepted	Pambudhi Kristyanto	
12	Safety Pin Bow Shackle	JLD 012	Crosby	6.5 ton	7/8 inch	-	√	-	-	11/6/2021	Accepted	Pambudhi Kristyanto	
13	Dry Container. Tare: 2580 kg. MGM: 6080 kg.	TRUI 5676274	INTERPOOL LIMITED	3500 KG	3000 x 2440 x 2580 mm (LxWxH)	-	√	√	-	11/6/2021	Accepted	Pambudhi Kristyanto	Need to Maintenance of ISO CORNER Section





**PT. INSPEKTINDO SINERGI PERSADA**  
**DAILY INSPECTION REPORT SUMMARY**



<b>Name &amp; address of employer for whom the thorough examination was made:</b>	<b>Address of premises at which the examination was made:</b>	<b>PO No. :</b>
<b>PT. PATRA DRILLING CONTRACTOR Balikpapan</b>	<b>PHM Handil Bravo 1 Jetty</b>	<b>RFI No. :</b>

No	Description	ID number	Manufacture	SWL/Payload	Size/Dim	Examination Type				Date of Inspection	Inspection Result	Performer	Remarks
						CoC	Visual	NDT	Load Testing				
14	4 legged wire rope sling	TBM/C/20/0074	TALIMAS	15.5 ton 0-45 deg	24 mm x 4 meters	-	v	-	-	11/6/2021	Accepted	Pambudhi Kristyanto	
15	Safety Pin Bow Shackle	JLD 005	Crosby	6.5 ton	7/8 inch	-	v	-	-	11/6/2021	Accepted	Pambudhi Kristyanto	
16	Safety Pin Bow Shackle	JLD 006	Crosby	6.5 ton	7/8 inch	-	v	-	-	11/6/2021	Accepted	Pambudhi Kristyanto	
17	Safety Pin Bow Shackle	JLD 007	Crosby	6.5 ton	7/8 inch	-	v	-	-	11/6/2021	Accepted	Pambudhi Kristyanto	
18	Safety Pin Bow Shackle	JLD 008	Crosby	6.5 ton	7/8 inch	-	v	-	-	11/6/2021	Accepted	Pambudhi Kristyanto	





**PT. INSPEKTINDO SINERGI PERSADA**  
**DAILY INSPECTION REPORT SUMMARY**



Name & address of employer for whom the thorough examination was made:					Address of premises at which the examination was made:					PO No. :			
PT. PATRA DRILLING CONTRACTOR Balikpapan					PHM Handil Bravo 1 Jetty					RFI No. :			
No	Description	ID number	Manufacture	SWL/Payload	Size/Dim	Examination Type				Date of Inspection	Inspection Result	Performer	Remarks
						CoC	Visual	NDT	Load Testing				

**NOTE :**  
  : Remove from Service  
  : Quarantine

Reported by,

*Pambudhi Kristyanto*  
*Lifting Inspector*

