

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance: **Suhardi Maricen**  
**Ermawan Eka S**

Customer: **PERTAMINA HULU**  
**MAHAKAM**

Service Date: **22-Jun-2021**

Periode : **Jun - Jul**

CRO No.:

Rig/Well :

No.	Service Description	Rig/Loc	Date of Inspection & Qty						TOTAL
			16-Jun	17-Jun	18-Jun	19-Jun	20-Jun	21-Jun	
1	Cargo Carrying Unit	BKP	1			2	1	1	5
2	Lever Hoist	BKP	2						2
3	Runway Beam	BKP	1	1	2	1	1	1	7
4	Snatch Block	BKP	2						2
5	Slewing Jib Davit	BKP		1					1
6	Beam Trolley	BKP	1	1					2
7	Beam Clamp	BKP					1		1
8	Wire Rope Sling 1-leg or 2-legs	BKP		2					2
9	Gantry	BKP		1					1
10	Shackle	BKP		6		4	1		11
11	Wire Rope Sling 3-leg or 4-legs	BKP				1			1
12	Chain Block	BKP			3			2	5
13	Polyester Sling	BKP					5		5
14	Pedestal Crane	BKP							
15	Pad Eye							6	6
<b>Equipment Rental</b>									
1	Water bag 3 tonnes	unit-day							
2	Water bag 12 tonnes	unit-day							
3	Load Cell 5 tonnes	unit-day							
4	Load Cell 30 tonnes	unit-day							
5	Wire rope tester	unit-day							
<b>PROVISION</b>									
7	Land Transportation	unit-day							
8	Meal allowance	man-day	2	2	2	2	2	2	14

**Suhardi Maricen**  
Personnel In Attendance

Approved by PHM sites INS SPV

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance: **Suhardi Maricen**  
**Ermawan Eka S**

Customer: **PERTAMINA HULU**  
**MAHAKAM**

Service Date: **29-Jun-2021**

Periode: **Jun - Jul**

CRO No.:

Rig/Well:

No.	Service Description	Rig/Loc	Date of Inspection & Qty						TOTAL
			23-Jun	24-Jun	25-Jun	26-Jun	27-Jun	28-Jun	
1	Cargo Carrying Unit			1					1
2	Lifting Frame With Pad Eye								
3	Other Below The Hook Lifting Devices			5			1		6
4	Overhead Crane				1				1
5	Pad Eye			4			4	19	27
6	Pedestal Crane		1		1				2
7	Runway Beam					1	1		2
8	Shackle			7					7
9	Wire Rope Sling 1-leg or 2-legs					4			4
10	Wire Rope Sling 3-leg or 4-legs						1		1
11									
12									
13									
14									
15									
<b>Equipment Rental</b>									
1	Water bag 3 tonnes	unit-day							
2	Water bag 12 tonnes	unit-day							
3	Load Cell 5 tonnes	unit-day							
4	Load Cell 30 tonnes	unit-day							
5	Wire rope tester	unit-day	1		1	1			3
<b>PROVISION</b>									
7	Land Transportation	unit-day							
8	Meal allowance	man-day	2	2	2	2	2	2	14

**Suhardi Maricen**  
Personnel In Attendance

**BUKTI H / JOKO S**  
Approved by PHM sites INS SPV

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance: **SUHARDI MARICEN**  
**ERMAWAN EKA S.**

Customer: **PERTAMINA HULU**  
**MAHAKAM**

Service Date: **6-Jul-2021**

Periode : **Jun - Jul**

CRO No.:

Rig/Well : **BEKAPAI**

No.	Service Description	Rig/Loc	Date of Inspection & Qty						TOTAL
			30-Jun	1-Jul	2-Jul	3-Jul	4-Jul	5-Jul	
1	Pad Eye	BKP	21	16					37
2	Runway Beam	BKP			1				1
3	Other Below The Hook Lifting Devices	BKP			2				2
4									
5									
6									
7									
8									
9									
10									
11									
12									
13									
14									
15									
<b>Equipment Rental</b>									
1	Water bag 3 tonnes	unit-day							
2	Water bag 12 tonnes	unit-day							
3	Load Cell 5 tonnes	unit-day							
4	Load Cell 30 tonnes	unit-day							
5	Wire rope tester	unit-day							
<b>PROVISION</b>									
7	Land Transportation	unit-day			1				1
8	Meal allowance	man-day	2	2	2				6

**SUHARDI MARICEN**  
Personnel In Attendance

**BUKTI H / JOKO S**  
Approved by PHM sites INS SPV