

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance:

**Leo Rante**  
**Yohanes Agus MS.**

Customer:

**PERTAMINA HULU**  
**MAHAKAM**

Service Date:

**Feb. 05 2021**

Periode :

**Feb. 2021**

CRO No.:

**0**

Rig/Well :

**PTK - Tanjung Batu**

No.	Service Description	Rig/Loc	Date of Inspection & Qty						TOTAL
			3-Feb	4-Feb	5-Feb	6-Feb	7-Feb	8-Feb	
1	Cargo Carrying Unit		2	4	3				9
2	Wire Rope Sling 3-leg or 4-legs				2				2
3	Shackle				4				4
4									
5									
6									
7									
8									
9									
10									
11									
12									
13									
14									
15									
<b>Equipment Rental</b>									
1	Water bag 3 tonnes	unit-day							
2	Water bag 12 tonnes	unit-day							
3	Load Cell 5 tonnes	unit-day							
4	Load Cell 30 tonnes	unit-day							
5	Wire rope tester	unit-day							
<b>PROVISION</b>									
7	Land Transportation	unit-day	1	1	1				3
8	Meal allowance	man-day	2	2	2				6

**Leo Rante / Yohanes Agus MS.**  
Personnel In Attendance

**Juharmet Vemberius**  
Approved by PHM sites SPV