

Inspection Services

No.	Descriptions	UOM	Dec-23						Total	Job Description
						1	2	3		
1	Jasa Radiografi Test	Days				1	1	1	3	Monday
2	Jasa Dye Penetrant Test	Joints				19	10		29	
3	Jasa Ultrasonic Test	Days				1	1	1	3	
4	Jasa Magnetic Particle Test	Days							0	Tuesday
5	Jasa Holiday Test	Days							0	
6	Jasa Hydrotest Pipeline/Flowline <i>* Prehydrotest dilakukan oleh Perusahaan</i>	AU							0	Wednesday
7	Jasa Hydrotest Pipeline/Flowline <i>* Prehydrotest dilakukan oleh Kontraktor</i>	AU							0	
8	Hydrotest Piping system dalam station	AU							0	
9	Jasa Sewa Perahu Motor	Days							0	Thursday

Consumable Usage Summary

No.	DESCRIPTION	UOM	Dec-23						Total	Job Description
						1	2	3		
1	Film 4x10"	EA				21	8	0	29	Friday
2	Film 4x15"	EA				0	0	0	0	

Personnel

No.	Name	Position	Working Period	Remarks	Job Description
1	Doni Katmel	COORDINATOR/MT/PT/UT	1 - 3 Desember 2023	3 Days	Saturday
2	Forsanto Tambun	AR	1 - 3 Desember 2023	3 Days	
3	Ian Larsen	OR	1 - 3 Desember 2023	3 Days	
4	Petrus Harry Nataldo	OR	1 - 3 Desember 2023	3 Days	
					Sunday

Prepared by:




PT. INSPEKTINDO SINERGI PERSADA

Name : Doni Katmel

Date : 4 Desember 2023

Approved by:



Name : Iwan Iswandi / Yudi Pranadita

Date : 14.12.2023



Inspection Services

No.	Descriptions	UOM	Dec-23							Total	Job Description
			11	12	13	14	15				
1	Jasa Radiografi Test	Days	1	1	1	1	1			5	<b>PROJECT :</b> RT in WORKSHOP TRIKASA M05 BYPASS PROJECT FOR M12 STATION (4x10 = 1 Sheets) RT in WORKSHOP TRIKASA M12 FLARE SYSTEM UPGRADING (4x10 = 2 Sheets) UT THICKNESS : PIPING 4" TRUNKLINE SUNGAI MAMBURUNGAN
2	Jasa Dye Penetrant Test	Joints		14						14	
3	Jasa Ultrasonic Test	Days	1	1		1	1			4	
4	Jasa Magnetic Particle Test	Days								0	<b>PROJECT :</b> DPI in WORKSHOP TRIKASA M12 FLARE SYSTEM UPGRADING (14 Joint) UT THICKNESS : PIPING 4" TRUNKLINE SUNGAI MAMBURUNGAN
5	Jasa Holiday Test	Days								0	
6	Jasa Hydrotest Pipeline/Flowline <i>* Prehydrotest dilakukan oleh Perusahaan</i>	AU								0	<b>PRODUKSI :</b> RT in TRUNKLINE (4x10 = 12 Sheets) RT in SPOOL LINE ANNULUS MBR 23 (4x10 = 10 Sheets)
7	Jasa Hydrotest Pipeline/Flowline <i>* Prehydrotest dilakukan oleh Kontraktor</i>	AU								0	
8	Hydrotest Piping system dalam station	AU								0	
9	Jasa Sewa Perahu Motor	Days								0	

Consumable Usage Summary

No.	DESCRIPTION	UOM	Dec-23							Total	Job Description
			11	12	13	14	15				
1	Film 4x10"	EA	3	0	22	8	0			33	<b>PROJECT :</b> UT THICKNESS : PIPING 6" TRUNKLINE SUNGAI MAMBURUNGAN <b>PRODUKSI :</b> RT in SPOOL LINE ANNULUS MBR 23 (4x10 = 8 Sheets)
2	Film 4x15"	EA	0	0	0	0	0			0	

Personnel

No.	Name	Position	Working Period	Remarks
1	Doni Katmel	COORDINATOR/MT/PT/UT	11 - 15 Desember 2023	7 Days
2	Forsanto Tambun	AR	11 - 15 Desember 2023	7 Days
3	Petrus Harry Nataldo	OR	11 - 15 Desember 2023	7 Days

Prepared by:



PT. INSPEKTINDO SINERGI PERSADA

Name : Doni Katmel

Date : 15 Desember 2023

Approved by:

Name : Iwan Iswandi / Yudi Pranadita

Date :