

PT. INSPEKTINDO SINERGI PERSADA
DAILY INSPECTION REPORT SUMMARY - NDT - MPI 2023

Name & address of employer for whom the thorough examination was made:				Address of premises at which the examination was made:					PO No. :	-	
Gedung Wisma Mulia. Jl Jend Gatot Subroto Suite 4301 No.42 Kuningan Barat, Jakarta Selatan, Indonesia				Duri Base Jl.Raya Duri-Pekanbaru KM 11.Riau					RFI No. :	-	
No	Description	ID Number	FA No	SWL/ Payload	NDT/MPI	UT Thickness	Date of Inspection	Date of Next Inspection	Inspection Result	Performer	Remarks
1	BULKER 98003	WCF-AB-12	CTF41098Y0057	-	✓	-	27 March 2023	27 March 2024	ACC	Darmendra	Thickness by SLB
2	TRIPORT 10843	WS-AB-17	CTF41408Y0142	-	✓	-	04 April 2023	04 April 2024	ACC	Darmendra	Thickness by SLB
3	BULKER 34020	WCF-AB-13	CTF32098Y0052	-	✓	-	12 April 2023	12 April 2024	ACC	Darmendra	Thickness by SLB
4	Bulker 34021	WS-AB-053	CTF32098Y0053	-	✓	✓	Jun 12, 2023	Jun 12, 2024	ACC	Darmendra	Thickness by ISP
5	Bulker 98002	WS-AB-052	CTF41098Y0056	-	✓	✓	Jun 14, 2023	Jun 14, 2024	ACC	Darmendra	Thickness by ISP
6	TRIPORT 10841	WS-AB-103	CTF41408Y0141	-	✓	✓	May 15, 2023	May 15, 2024	ACC	Darmendra	Thickness by ISP

Reported by,

Darmendra

Inspector