

Certificate Of Thorough Examination



Client	Schlumberger	hlumberger Division							
Date of This Examination		This Certificate Number		Date of Next Examination Previ		Previous Cer	evious Certificate Number		
18/02/2015		ISP.HS.SLB 14770R/09/14.V		18/02/2016					
Date of Last Load Test		Certificate Number For Load Test				ast Tested	Tested by Company		
				Inspektindo Sinergi persada					
Identity No	Serial Num	ber	Tare Mass	Safe Working Load	Maximum Gr	ross Mass Proof Load Applied			
SLB 14770R									
Equipment Description									
Length Number of pad eyes									
Width				Position of pad eyes					
Height				Inspection Location	Wireline-JI.Ra	JI.Raya Duri-Pekanbaru KM11.Riau			
Inspection Comments									
				Was the examination carried out :					
Is this the first examination assembly at a new site	within an interval of 6 m	onths? Yes 🗌 No 🗹							
If the answer to the Previous question is Yes Yes No has the equipment been installed correctly?						Y	es 🖌	No 🗌	
has the equipment be	en installed cor	In accordance with an ex	xamination scheme? Yes 🗹 No 🗌						
		After the occurrence of exceptional circumstance?							
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none state NONE)									
Is the above a defect with intimidate danger to persons?					No	No			
Is the above a defect which is not yet but could become a danger to persons: (If YES state the date by when)									
Particulars of any repair, renewal or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none state NONE)									
none									
IS THIS EQUIPMENT FIT FOR PURPOSE?						Yes	Yes		
Inspector Name & Signature				Authenticator Name & Signature					
Qualification of Inspec	tor :								

