

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance: **Deny Herzaldi**  
**Ermawan Eka S**

Customer: **PERTAMINA HULU**  
**MAHAKAM**

Service Date: **12-Oct-2021**

Periode : **Sep-Oct**

CRO No.:

Rig/Well : **CPA (HCA)**

No.	Service Description	Rig/Loc	Date of Inspection & Qty						TOTAL	
			6-Oct	7-Oct	8-Oct	9-Oct	10-Oct	11-Oct		12-Oct
1	Gantry	CPA						1		1
2										
3										
4										
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
<b>Equipment Rental</b>										
1	Water bag 3 tonnes	unit-day								
2	Water bag 12 tonnes	unit-day								
3	Load Cell 5 tonnes	unit-day								
4	Load Cell 30 tonnes	unit-day						1		1
5	Wire rope tester	unit-day								
<b>PROVISION</b>										
7	Land Transportation	unit-day						1		1
8	Meal allowance	man-day						2		2

**Deny Herzaldi**  
Personnel In Attendance

**Ahmadan F / Imam D.W**  
Approved by PHM sites INS SPV