PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET

Personnel In Attendance	**Kelana syahputra**	Customer:	PHKT	Date :	9-Sep-23
Period:	August & September 202	Contract/ PO Non:	4300012373	Our Ref:	
Day Rate:		Rig / Well:	Inspection Area - PT Citra Tubindo		
Per Diem Rate :				Form No. :	

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING		
				Day	Mob/ Demob (USD)	Per diem (Day)
21-Aug-23	PHKT	08.00-17.00	Inspection Process External Coating Tubing 3 1/2"	1		
22-Aug-23	PHKT	08.00-17.00	Inspection Process Threading Pup Joint 3 1/2"	1		
23-Aug-23	PHKT	08.00-17.00	Inspection Process Threading Pup Joint 3 1/2"	1		
24-Aug-23	PHKT	08.00-17.00	Inspection Process Threading Pup Joint 3 1/2"	1		
25-Aug-23	PHKT	08.00-17.00	Inspection Process Threading Pup Joint 3 1/2"	1		
26-Aug-23	PHKT	08.00-17.00	Inspection Process Threading Pup Joint 3 1/2"	1		
27-Aug-23	PHKT	08.00-17.00	Inspection Process Threading Pup Joint 3 1/2"	1		
28-Aug-23	PHKT	08.00-17.00	Inspection Process Threading Pup Joint 3 1/2"	1		
29-Aug-23	PHKT	08.00-17.00	Inspection Process Threading Pup Joint 3 1/2"	1		
30-Aug-23	PHKT	08.00-17.00	Inspection Process Threading Pup Joint 3 1/2"	1		
31-Aug-23	PHKT	08.00-17.00	Inspection Process Threading Pup Joint 3 1/2"	1		
1-Sep-23	PHKT	08.00-17.00	Inspection Process Threading Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT	1		
2-Sep-23	PHKT	08.00-17.00	Inspection Process Threading Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT & Review Document Release Batch 1 RO-04	1		
3-Sep-23	PHKT	08.00-17.00	Inspection Process Threading Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT	1		
4-Sep-23	PHKT	08.00-17.00	Inspection Process Threading Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT	1		
5-Sep-23	PHKT	08.00-17.00	Inspection Process Threading Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT	1		
6-Sep-23	PHKT	08.00-17.00	Inspection Process Threading Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT	1		
7-Sep-23	PHKT	08.00-17.00	Inspection Process Threading Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT	1		
8-Sep-23	PHKT	08.00-17.00	Inspection Process Threading Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT & Review Document Release Batch 1 RO-04	1		
9-Sep-23	PHKT	08.00-17.00	Inspection Process Threading & Bucking Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT	1		
				20		
			TOTAL (USD)			
			GRAND TOTAL			

* If Applicable

Personnel In Attendance

Contractor Representative

Rig Representative

The Company Representative

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET

Personnel In Attendance	**Kelana syahputra**	Customer:	PHKT	Date :	20-Sep-23
Period:	September 2023	Contract/ PO Non:	4300012373	Our Ref:	
Day Rate:		Rig / Well:	Inspection Area - PT Citra Tubindo		
Per Diem Rate :				Form No. :	

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING		
				Day	Mob/ Demob (USD)	Per diem (Day)
10-Sep-23	PHKT	08.00-17.00	Inspection Process Bucking Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT	1		
11-Sep-23	PHKT	08.00-17.00	Inspection Process Threading Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT & Review Document Release Batch 1 RO-04	1		
12-Sep-23	PHKT	08.00-17.00	Inspection Process Threading Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT & Review Document Release Batch 1 RO-04	1		
13-Sep-23	PHKT	08.00-17.00	Inspection Process Bucking Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT	1		
14-Sep-23	PHKT	08.00-17.00	Inspection Process Bucking & External Coatiung Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT	1		
15-Sep-23	PHKT	08.00-17.00	Inspection Process Bucking & External Coatiung Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT	1		
16-Sep-23	PHKT	08.00-17.00	Inspection Process Bucking & External Coatiung Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT	1		
17-Sep-23	PHKT	08.00-17.00	Inspection Process Bucking & External Coatiung Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT	1		
18-Sep-23	PHKT	08.00-17.00	Inspection Process External Coatiung Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT	1		
19-Sep-23	PHKT	08.00-17.00	Inspection Process External Coatiung Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT ,Review Document Release Batch 2.	1		
20-Sep-23	PHKT	08.00-17.00	Inspection Process External Coatiung Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT ,Review Document Release Batch 2.	1		
				11		
			TOTAL (USD)			
			GRAND TOTAL			

* If Applicable

Personnel In Attendance | Contractor Representative | Rig Representative | The Company Representative