



PT. INSPEKTINDO SINERGI PERSADA
 SERVICE TIMESHEET HYDROTEST - MAI DEPT
 PT. Medco E & P
 Contract Number : 3510007418
 Location : Rimau Blok

Period : Jun-23

No.	Descriptions	UOM	Jun-23							Total	Job Description
			5	6	7	8	9	10	11		
1	Jasa Radiografi Test	Days								0	
2	Jasa Dye Penetrant Test	Joints								0	
3	Jasa Ultrasonic Test	Days								0	
4	Jasa Magnetic Particle Test	Days								0	Verification Equipment for Hydrotest by Maintenance & HSE Dept.
5	Jasa Holiday Test	Days								0	
6	Jasa Hydrotest Pipeline/Flowline <i>*Pretest dilakukan oleh Perusaahaan</i>	AU								0	
7	Jasa Hydrotest Pipeline/Flowline <i>*Pretest dilakukan oleh Kontraktor</i>	AU								0	
8	Hydrotest Piping system dalam station	AU		1	1	1	1	1	1	6	
9	Jasa Sewa Perahu Motor	Days								0	

Consumable Usage Summary

No.	DESCRIPTION	UOM	Jun-23				Total
			5	6	7	8	
1	Film 4x10"	EA					0
2	Film 4x15"	EA					0

Personnel

No.	Name	Position	Working Period	Remarks	
2	RISKI ARIANTO HARAHAP	TEKNISI	06-11 Juni 2023	6 Day	Saturday
3	MUHAMMAD FHADLY	TEKNISI	06-11 Juni 2023	6 Day	Friday
4					Thursday
5					Wednesday

Approved by:

Name: *(Signature)*
 Head of MAI Dept - Rimau Block



Name: *(Signature)*
 COORDINATOR