

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: Satfiahil, Lamhot, Faro, Manggara
 Period: June-July 2023
 Day / Rate: _____
 Per Diem Rate: _____

Customer: PT. Schlumberger Indonesia - D&M
 Contract/ PO No: _____
 Rig / Well: Duri Base

Date: _____
 Our Ref: _____
 Form No: _____

Billing Date	Rig / Loc*	Time*	ACTIVITY (OVERTIME)	Hours	W/O Number	BILLING			Company Representative Signature
						BORG	Segment		
1-Jul-23	Duri Base	10:00-22:00	String stab 9 1/2"HS_BMS 10S02 (MPI Inspection), Near Bit, Steel, Integral Spiral Blade - 12 1/4"HS_GP 6924-44 (MPI Inspection), String stab 9 7/8"HS_GP 6924-82 (MPI Inspection), Near bit stab 12 1/4"HS_GP 6924-46 (MPI Inspection), String stab 9 3/8"HS_GP 6924-87 (MPI Inspection), Bottle Neck_SBD 1317 (MPI Inspection), Bottle Neck_GP 6968-37 (MPI Inspection)	11 ✓	WCM_020723_240-256_DURI		D&M	<i>[Signature]</i>	
2-Jul-23	Duri Base	08:00-18:00	String stab 1 1/4"HS_GP 7127-31 (MPI Inspection), String stab 9 3/8"HS_83297 H (MPI Inspection), String stab 9 1/2"HS_BBS 592303 (MPI Inspection), String stab 9 3/4"HS_BBS 527402 (MPI Inspection), 1 Set Mud Motor ASSY A675_18415 (MPI Inspection), 1 Set Mud Motor LILIN ASSY 825_20629 (MPI Inspection), String stab 7 1/2"HS_GP 9924-09 (MPI Inspection)	9 ✓	WCM_020723_240-256_DURI		D&M	<i>[Signature]</i>	
3-Jul-23	Duri Base	17:00-21:00	NMPC 6" SBD 3822 (DPI Inspection), JAR NOV_474-651289 (MPI Inspection), 1 Set Mud Motor ASSY 675_05488 (MPI Inspection), Bottle Neck_JOP23-OSS-006 (MPI Inspection), EMT 6 5 RYTON GAP SUB_4-1/2"IF -GSB0044R (MPI Inspection), Float sub_SBD 9925 (MPI Inspection)	4 ✓	To Be Created		D&M	<i>[Signature]</i>	
4-Jul-23	Duri Base	17:00-21:00	SFSA 6_1793 (DPI Inspection), Hole Opener 8 1/2"HS_HQ0850-03-05-23-SA (MPI Inspection), Bullnose_BU0850 RP.01_09.22 SA (MPI Inspection), Crossover_SBD 14651 (MPI Inspection), Non Mag Float sub_NN (MPI Inspection), 1 Set Mud Motor ASSY 958_06220015 (MPI Inspection), 1 Set Mud Motor ASSY 825_180456 (MPI Inspection), NMDC 6" AIVAS 6757365 (MPI Inspection)	4 ✓	To Be Created		D&M	<i>[Signature]</i>	
5-Jul-23	Duri Base	17:00-22:00	2 ea URRB 825_NN (MPI Inspection), Transmission Shaft 825_1801017 (MPI Inspection), Transmission Shaft 825_1801003 (MPI Inspection), Splined Mandrel 825_1802028 (MPI Inspection), Bearing Nut 825_NN (MPI Inspection), Bearing Housing 825_1802007 (MPI Inspection), Splined Mandrel 825_1802028, LRRB_NN (MPI Inspection), Drive sub 825_0070717 (MPI Inspection), NMDC_99476H (MPI Inspection)	5 ✓	To Be Created		D&M	<i>[Signature]</i>	
TOTAL (hours)				33 ✓					

* If Applicable

[Signature]
 Satfiahil Lamhot, Faro
 Personnel In Attendance

[Signature]
 Satfiahil
 ISP Inspector

[Signature]
 SLB Maintenance Technician

[Signature]
 Anson Kimmon
 SLB Maintenance Supervisor