

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:

Deny Herzaldi
Agus Salim Asbar

Customer:

PERTAMINA HULU
MAHAKAM

Service Date:

14-Jun-2022

Periode :

JUN - JUL

CRO No.:

Rig/Well :

NPU

No.	Service Description	Rig/Loc	Date of Inspection & Qty						TOTAL	
			8-Jun	9-Jun	10-Jun	11-Jun	12-Jun	13-Jun		14-Jun
1	Shackle	NPU	21	9						30
2	Eyebolts	NPU	4	28						32
3	Transportation Containers	NPU			6		2	2	2	12
4	Pad Eye	NPU				4	4	4		12
5	Slewing Jib / Davit	NPU				1	2			3
6	Runway Beam	NPU				10	4	8	7	29
7	Jack	NPU					1			1
8	Webbing Sling	NPU					8		11	19
9	Beam Trolley	NPU						4		4
10	Chain Hoist	NPU						1	1	2
11										
12										
13										
14										
15										
Equipment Rental										
1	Water bag 3 tonnes	unit-day	-	-	-	-	-	-	-	-
2	Water bag 15 tonnes	unit-day	-	-	-	-	-	-	-	-
3	Load Cell 5 tonnes	unit-day	-	-	-	-	-	-	-	-
4	Load Cell 30 tonnes	unit-day	-	-	-	-	-	-	-	-
5	Wire rope tester equipment	unit-day	-	-	-	-	-	-	-	-
PROVISION										
7	Land Transportation	unit-day	1	-	-	-	-	-	-	1
8	Daily Personnel allowance	man-day	2	2	2	2	2	2	2	14

Deny Herzaldi
Personnel In Attendance

Bambang Yudiono
Approved by PHM sites INS SPV