

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: **1. Erwin Nugraha**
2. Reza Achmad

Customer: **PERTAMINA HULU MAHAKAM**

Service Date:

Periode : **Nov - Des**

CRO No.: **8532803**

Rig/Well : **CPU**

No.	Service Description	Rig/Loc	Date of Inspection & Qty						TOTAL
			18-Nov	19-Nov	20-Nov	21-Nov	22-Nov	23-Nov	
1	Runway Beam		3						3
2	Pad Eye		2	4					6
3	Beam Trolley		2						2
4	Shackle			21	4				25
5	Polyester Sling			7					7
6	Powered Hoist				1				1
7	Wire Rope Sling 1-leg or 2-legs				9				9
8	Eye Bolt				2				2
9									
10									
11									
12									
13									
14									
15									
Equipment Rental									
1	Water bag 3 tonnes	unit-day							
2	Water bag 12 tonnes	unit-day							
3	Load Cell 5 tonnes	unit-day							
4	Load Cell 30 tonnes	unit-day							
5	Wire rope tester	unit-day							
PROVISION									
7	Land Transportation	unit-day							
8	Meal allowance	man-day							

Personnel In Attendance

Approved by PHM sites INS SPV