


# WORK TIME SHEET


Employee Name: - MUHAMMAD FADLY (INSPECTOR) - BOGA M PARDEDE (ASS. INSPECTOR)	RFI Number: RFI 23-164	Location: PT. UNITED SIMO PERKASA ON BOARD - HOLMEN PACIFIC
Customer Name: <b>VALLIANZ</b>	PO/WO Number:	


Date & Day	Scope of Work	Start Time	Finish Time
Oct 31, 2023	- Review Document	08.00	
	- Conduct Visual Inspection & Dimensional Conformity :		
	1. 2 EA Tow Bridle Chain		
	2. 1 EA EMERGENCY Tow Bridle Chain		
	3. 1 EA Tow Pennant wire		
	4. 1 EA EMERGENCY Tow Pennant wire		
	- Install Tag ID		12.00

### Consumable Material Usage

Date & Day	Material Usage and Quantity	Remark
Oct 31, 2023	- 10 TAG / Name Plak = 2 EA	
	- Aluminium ferrule = 2 EA	
	- Wire 3 mm = 50 cm.	

Client Signature :  Date : 31/10/2023  
 Name : KURNO SUBARWADI  
 Company : VALLIANZ

Employee Signature :  MUHAMMAD FADLY



Ps. Kindly return this timesheet to PT. Rigspek Perkasa upon completion the work.

### PT. RIGSPEK PERKASA

Komplek Kawasan Industri Sekupang  
 Kav. No.13, Batam 29428, Indonesia  
 Tel : +62 (0) 778 324747 / 324749  
 Fax : +62 (0) 778 321338



Management System  
 ISO 9001:2015  
 www.tuv.com  
 ID 310503224

