



## PT.Inspektindo Sinergi Persada DAILY INSPECTION REPORT SUMMARY



Name & address of employer for whom the thorough examination was made:							Address of premises at which the examination was made:						PO No. :	TBA		
PT. Schlumberger Indonesia							Duri Base						RFI No. :	TBA		
No	Description	Asset Number	Body Number	Manufacture	MAWP	Size/Dim	Examination Type						Date of Inspection	Inspection Result	Performer	Remarks
							Doc. Review		Visual	DC	NDT (MPI)	NDT (UTG)				
							CoC	PIR								
1	Bulker	CTF41098Y0057	CTF98003	PT. Sanggar Sarana Baja	40 Psi	TBA	✓	-	✓	✓	✓	✓	04 January 2024	Accepted	Elicohen	Done
2	Bulker	CTF32098Y0052	CTF34020	Meng Fatt Co. Pte Ltd	40 Psig	TBA	Waiting for Reverse Engineering	-	✓	✓	✓	✓	04 January 2024	Accepted	Elicohen	COI has been issued. Waiting to Reverse Engineering Result
3	Banana Tank	CTF41198Y0054	CTF34022	TBA	TBA	TBA	Waiting for Reverse Engineering	-	✓	✓	✓	✓	18 January 2924	Accepted	Elicohen	Waiting for reverse engineering
4	Banana Tank	CTF32008Y0147	CTF8005	Al Shirawi Equipment	0.24 Mpa	TBA	✓	-	✓	✓	✓	✓	11 January 2024	Accepted	Elicohen	Done
5	Banana Tank	CTF32008Y0148	CTF8006	Al Shirawi Equipment	30 Psig	TBA	✓	-	✓	✓	✓	✓	04 January 2024	Accepted	Elicohen	Done
6	Banana Tank	CTF41098Y0055	CTF80341	Al Shirawi Equipment	0.24 Mpa	TBA	✓	-	✓	✓	✓	✓	03 February 2024	Quarantine	Darmendra	Found 14 point Welding Incomplete Penetration on Weld joint. Need to repair the weld area.
7	Banana Tank	CTF32009Y0068	CTF9001	TBA	TBA	TBA	✓	-								
8	Banana Tank	CTF21514Y0171	CTF51405	TBA	TBA	TBA	✓	-								
9	Bulker	CTF32098Y0053	CTF34021	Meng Fatt Co. Pte Ltd	40 Psig	TBA	Waiting for Reverse Engineering	-	✓	✓	✓	✓	05 January 2024	Accepted	Elicohen	Done
10	Banana Tank	CTF32008Y0146	CTF7013	Al Shirawi Equipment	0.24 Mpa	TBA	✓	-	✓	✓	✓	✓	29 January 2024	Accepted	Darmendra	Reporting On Progress
11	Bulker	CTF41098Y0056	CTF98002	PT. Sanggar Sarana Baja	40 Psi	TBA	✓	-	✓	✓	✓	✓	05 January 2024	Accepted	Elicohen	Done
12	Banana Tank	CTF21512Y0100	CTF60006	TBA	TBA	TBA	✓	-								On Progress





**PT.Inspektindo Sinergi Persada**  
**DAILY INSPECTION REPORT SUMMARY**



<b>Name &amp; address of employer for whom the thorough examination was made:</b>	<b>Address of premises at which the examination was made:</b>	<b>PO No. :</b>	<b>TBA</b>
<b>PT. Schlumberger Indonesia</b>	<b>Duri Base</b>	<b>RFI No. :</b>	<b>TBA</b>

No	Description	Asset Number	Body Number	Manufacture	MAWP	Size/Dim	Examination Type						Date of Inspection	Inspection Result	Performer	Remarks
							Doc. Review	Visual	DC	NDT (MPI)	NDT					
13	Banana Tank	CTF21512Y0099	CTF60004	Gemala Saranaupaya	30 Psig	TBA	✓	-	✓	✓	✓	✓	08 January 2024	Accepted	Elicohen	Done
14	Banana Tank	CTF21512Y0101	CTF60005	TBA	TBA	TBA	Waiting from SLB	-	✓	✓	✓	✓	25 January 2024	Accepted	Elicohen	Reporting On Progress
15	Banana Tank	CTF21514Y0170	CTF51404	TBA	TBA	TBA	✓	-								
16	Banana Tank	CTF21512Y0097	CTF60002	Gemala Saranaupaya	30 Psig	TBA	✓	-	✓	✓	✓	✓	23 January 2024	Accepted	Elicohen	Done
17	Banana Tank	CTF21512Y0098	CTF60003	TBA	TBA	TBA	Waiting from SLB	-								
18	Banana Tank	CTF21512Y0096	60001	Gemala Saranaupaya	30 Psig	TBA	✓	-	✓	✓	✓	✓	15 January 2024	Accepted	Elicohen	Done
19	Tripod 1	CTF41408Y0142	N/A	Al Shirawi Equipment	30 Psig	TBA	✓	-	✓	✓	✓	✓	04 January 2024	Accepted	Elicohen	Done
20	Tripod 2	CTF41408Y0141	N/A	A; Shirawi Equipment	30 Psig	TBA	✓	-	✓	✓	✓	✓	04 January 2024	Accepted	Elicohen	Done

**Legend :**

CoC = Certificate of Conformity ; PIR = Previous Inspection Report ; NDT = Non-Destructive Test ;; DC = Dimensional Conformity ; MAWP = Maximum Allowable Working Pressure

**NOTE :**

- : Remove from Service
- : Quarantine
- Priority
- Coloum of examination type subject to change according to approved scope of work

Reported by,

***Elicohen & Darmendra***  
***Position***

