

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:

Deny Herzaldi
Nico Achmad

Customer:

PERTAMINA HULU
MAHAKAM

Service Date:

20-Dec-2022

Periode :

DEC- JAN

CRO No.:

Rig/Well :

NPU

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL	
			14-Dec	15-Dec	16-Dec	17-Dec	18-Dec	19-Dec	20-Dec		
1	Chain Hoist	NPU	1							1	
2	Jack	NPU	1							1	
3	Transportation Containers	NPU	4					6	1	11	
4	Pad Eye	NPU		7						7	
5	Runway Beam	NPU		5	3					8	
6	Slewing Jib / Davit	NPU		6	1					7	
7	Ginpoles	NPU			2	3	12			17	
8	Beam Trolley	NPU			1					1	
9	Eyebolts	NPU				20				20	
10	Shackle	NPU							10	10	
11	Wire Rope Sling 1-leg or 2-legs	NPU							3	3	
12	Wire Rope Sling 3-leg or 4-legs	NPU							1	1	
13											
14											
15											
Equipment Rental											
1	Water bag 3 tonnes	unit-day	-	-	-	-	-	-	-	-	
2	Water bag 15 tonnes	unit-day	-	-	-	-	-	-	-	-	
3	Load Cell 5 tonnes	unit-day	-	-	-	-	-	-	-	-	
4	Load Cell 30 tonnes	unit-day	-	-	-	-	-	-	-	-	
5	Wire rope tester equipment	unit-day	-	-	-	-	-	-	-	-	
PROVISION											
7	Land Transportation	unit-day	-	-	-	-	-	-	-	1	1
8	Daily Personnel allowance	man-day	2	2	2	2	2	2	2	14	

Deny Herzaldi

Personnel In Attendance

Bambang YUDIONO

Bambang Yudiono

Approved by PHM sites INS SPV

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:

Deny Herzaldi
Nico Achmad

Customer:

PERTAMINA HULU
MAHAKAM

Service Date:

3-Jan-2023

Periode :

DEC- JAN

CRO No.:

Rig/Well :

NPU

No.	Service Description	Rig/Loc	Date of Inspection & Qty						TOTAL	
			28-Dec	29-Dec	30-Dec	31-Dec	1-Jan	2-Jan		3-Jan
1	Slewing Jib / Davit	NPU	1					2		3
2	Runway Beam	NPU	1					8	7	16
3	Ginpoles	NPU	6	5					5	16
4	Eyebolts	NPU		10		12	22			44
5	Forklifts	NPU			1					1
6	Chain Hoist	NPU					3			3
7	Webbing Sling	NPU					4			4
8	Shackle	NPU					2			2
9	Pad Eye	NPU						4		4
10										
11										
12										
13										
14										
15										
Equipment Rental										
1	Water bag 3 tonnes	unit-day	-	-	-	-	-	-	-	-
2	Water bag 15 tonnes	unit-day	-	-	-	-	-	-	-	-
3	Load Cell 5 tonnes	unit-day	-	-	-	-	-	-	-	-
4	Load Cell 30 tonnes	unit-day	-	-	-	-	-	-	-	-
5	Wire rope tester equipment	unit-day	-	-	-	-	-	-	-	-
PROVISION										
7	Land Transportation	unit-day	1	-	-	-	-	-	-	1
8	Daily Personnel allowance	man-day	2	2	2	2	2	2	2	14

Deny Herzaldi
Personnel In Attendance

Bambang YUDICHO

Pakop. D/Bambang.Y
Approved by PHM sites INS SPV

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:

Deny Herzaldi
Nico Achmad

Customer:

PERTAMINA HULU
MAHAKAM

Service Date:

10-Jan-2023

Periode :

JAN- FEB

CRO No.:

Rig/Well :

NPU

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			4-Jan	5-Jan	6-Jan	7-Jan	8-Jan	9-Jan	10-Jan	
1	Runway Beam	NPU	4						3	7
2	Slewing Jib / Davit	NPU	1						1	2
3	Ginpoles	NPU	6	9	7	14	1		6	10
4	Shackle	NPU	10		13					23
5	Webbing Sling	NPU					12			12
6	Chain Hoist	NPU					1			1
7	Beam Trolley	NPU						1		1
8										
9										
10										
11										
12										
13										
14										
15										
Equipment Rental										
1	Water bag 3 tonnes	unit-day	-	-	-	-	-	-	-	-
2	Water bag 15 tonnes	unit-day	-	-	-	-	-	-	-	-
3	Load Cell 5 tonnes	unit-day	-	-	-	-	-	-	-	-
4	Load Cell 30 tonnes	unit-day	-	-	-	-	-	-	-	-
5	Wire rope tester equipment	unit-day	-	-	-	-	-	-	-	-
PROVISION										
7	Land Transportation	unit-day	-	-	-	-	-	-	-	-
8	Daily Personnel allowance	man-day	2	2	2	2	2	2	2	14

Deny Herzaldi

Personnel In Attendance

Bambang YUDIONO

Bambang.Y/Pakop.D

Approved by PHM sites INS SPV

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:

Deny Herzaldi
Nico Achmad

Customer:

PERTAMINA HULU
MAHAKAM

Service Date:

17-Jan-2023

Periode :

JAN- FEB

CRO No.:

Rig/Well :

NPU

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			11-Jan	12-Jan	13-Jan	14-Jan	15-Jan	16-Jan	17-Jan	
1	Ginpoles	NPU	12		9	7	3			31
2	Runway Beam	NPU		7		1				8
3	Pad Eye	NPU		7						7
4	Slewing Jib / Davit	NPU		3		4				7
5	Beam Clamp	NPU					5			5
6	Wire Rope Sling 1-leg or 2-legs	NPU					17			17
7	Wire Rope Sling 3-leg or 4-legs	NPU					1	3		4
8	Shackle	NPU						16		16
9	Webbing Sling	NPU						11		11
10										
11										
12										
13										
14										
15										
Equipment Rental										
1	Water bag 3 tonnes	unit-day	-	-	-	-	-	-	-	-
2	Water bag 15 tonnes	unit-day	-	-	-	-	-	-	-	-
3	Load Cell 5 tonnes	unit-day	-	-	-	-	-	-	-	-
4	Load Cell 30 tonnes	unit-day	-	-	-	-	-	-	-	-
5	Wire rope tester equipment	unit-day	-	-	-	-	-	-	-	-
PROVISION										
7	Land Transportation	unit-day	-	-	-	-	-	-	-	-
8	Daily Personnel allowance	man-day	2	2	2	2	2	2	2	14

Deny Herzaldi

Personnel In Attendance

Bambang YUDI

Bambang.Y/Pakop.D

Approved by PHM sites INS SPV

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:

Deny Herzaldi
Nico Achmad

Customer:

PERTAMINA HULU
MAHAKAM

Service Date:

24-Jan-2023

Periode :

JAN- FEB

CRO No.:

Rig/Well :

NPU

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			18-Jan	19-Jan	20-Jan	21-Jan	22-Jan	23-Jan	24-Jan	
1	Jack	NPU	1							1
2	Chain Hoist	NPU	5							5
3	Eyebolts	NPU	21	20	10					51
4	Shackle	NPU	7		27					34
5	Crane include Pedestal Crane, Mobile Land Crane, Overhead crane	NPU		1						1
6	Runway Beam	NPU		1						1
7										
8										
9										
10										
11										
12										
13										
14										
15										
Equipment Rental										
1	Water bag 3 tonnes	unit-day	-	-	-	-	-	-	-	
2	Water bag 15 tonnes	unit-day	-	-	-	-	-	-	-	
3	Load Cell 5 tonnes	unit-day	-	-	-	-	-	-	-	
4	Load Cell 30 tonnes	unit-day	-	-	-	-	-	-	-	
5	Wire rope tester equipment	unit-day	-	-	-	-	-	-	-	
PROVISION										
7	Land Transportation	unit-day	-	-	-	-	-	-	-	
8	Daily Personnel allowance	man-day	2	2	2	-	-	-	-	6

Deny Herzaldi

Personnel In Attendance

Bambang YUDI...

Bambang.Y/Pakop.D

Approved by PHM sites INS SPV