

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance:
1. Gunawan R.
2. Abdillah M.

Customer:
PERTAMINA HULU MAHAKAM

Service Date:
13 July 2020

Periode : **July 2020**

CRO No.: **4200139209**

Rig/Well : **NORTH PROCESSING UNIT**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL	
			7-Jul	8-Jul	9-Jul	10-Jul	11-Jul	12-Jul	13-Jul		
1	Shackle	NPU	20						14	12	46
2	Slewing Jib Davit	NPU						6		1	7
3	Runway Beam	NPU						4			4
4	Chain block	NPU			3						3
5	Ginpole	NPU	1	8	1	5					15
6	Cargo Carrying Unit including lifting set	NPU			1						1
7	Wire rope sling 3-leg or 4-leg	NPU							6		6
8	Hydraulic Ram & Jack	NPU		2							2
9	Forklift	NPU		1							1
10	Polyster sling	NPU									9
11	Pad eye	NPU						7			7
12	Wire rope sling 1-leg or 2-leg	NPU							2		2
TOTAL			21	8	4	9	17	22	22	22	103

		Equipment Rental	
1	Water bag 3 tonnes	unit-day	0
2	Water bag 12 tonnes	unit-day	0
3	Load Cell 5 tonnes	unit-day	0
4	Load Cell 30 tonnes	unit-day	0
5	Wire rope tester	unit-day	0

		PROVISION	
6	Land Transportation	unit-day	0
7	Meal allowance	man-day	0

Gunawan R.

Bambang Yudianto
14 JUL 2020
Bambang Y

Personnel In Attendance

Approved by PHM sites INS SPV