

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance: **Suhardi Maricen**  
**Ermawan E.S**

Customer: **PERTAMINA HULU**  
**MAHAKAM**


Service Date: **10-Feb-2021**


Periode: **Nov - Jan**

CRO No.: **0**

Rig/Well: **SPU**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			5-Feb	6-Feb	7-Feb	8-Feb	9-Feb	10-Feb	11-Feb	
1	Shackle	SPU	24		34	10	25	21		114
2	Beam Clamp	SPU	1							1
3	Plate Handling Clamp	SPU	1							1
4	Pedestal Crane	SPU		1						1
5	Runway Beam	SPU				1				1
6	Slewing Jib Davit	SPU				1				1
7	Polyester Sling	SPU					4			4
8	Chain Block	SPU					1			1
9	Other Below The Hook Lifting Devices	SPU					1			1
10	Cargo Carrying Unit	SPU						1		1
11										
12										
13										
14										
15										
<b>Equipment Rental</b>										
1	Water bag 3 tonnes	unit-day								
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0		
3	Load Cell 5 tonnes	unit-day								
4	Load Cell 30 tonnes	unit-day	1	1						2
5	Wire rope tester	unit-day	1	1						2
<b>PROVISION</b>										
7	Land Transportation	unit-day								
8	Meal allowance	man-day								

  
**Suhardi Maricen**  
 Personnel In Attendance

  
**Isyudanto / Gunawan**  
 Approved by PHM sites INS SPV

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance: **Suhardi Maricen**  
**Ermawan E.S**

Customer: **PERTAMINA HULU**  
**MAHAKAM**

Service Date: **28-Jan-2021**

Periode : **Nov - Jan**

CRO No.: **0**

Rig/Well : **SPU**

No.	Service Description	Rig/Loc	Date of Inspection & Qty						TOTAL	
			22-Jan	23-Jan	24-Jan	25-Jan	26-Jan	27-Jan		28-Jan
1	Chain Block	SPU	1						1	2
2	Runway Beam	SPU	2							2
3	Beam Trolley	SPU	1							1
4	Pedestal Crane	SPU		IP	IP	1	IP	1		2
5	Slewing Jib Davit	SPU			2					2
6	Beam Clamp	SPU			1					1
7	Wire Rope Sling 1-leg or 2-legs	SPU			3					3
8	Cargo Carrying Unit	SPU			1				2	3
9	Shackle	SPU			6				1	7
10										
11										
12										
13										
14										
15										

**Equipment Rental**

1	Water bag 3 tonnes	unit-day								
2	Water bag 12 tonnes	unit-day	1	1	1	1	1	1	1	7
3	Load Cell 5 tonnes	unit-day								
4	Load Cell 30 tonnes	unit-day	1	1	1	1	1	1	1	7
5	Wire rope tester	unit-day	1	1	1	1	1	1	1	7

**PROVISION**

7	Land Transportation	unit-day								
8	Meal allowance	man-day								

**Suhardi Maricen**  
Personnel In Attendance

**Isyudanto / Gunawan**  
Approved by PHM sites INS SPV



**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance: **Suhardi Maricen**  
**Ermawan E.S**

Customer: **PERTAMINA HULU**  
**MAHAKAM**

Service Date: **4-Feb-2021**

Periode : **Nov - Jan**

CRO No.: **0**

Rig/Well : **SPU**

No.	Service Description	Rig/Loc	Date of Inspection & Qty						TOTAL	
			29-Jan	30-Jan	31-Jan	1-Feb	2-Feb	3-Feb		4-Feb
1	Pedestal Crane	SPU	IP	1		1				2
2	Forklift	SPU			1					1
3	Overhead Crane	SPU						1		1
4	Plate Handling Clamp	SPU					1			1
5	Wire Rope Sling 1-leg or 2-legs	SPU					2		1	3
6	Wire Rope Sling 3-leg or 4-legs	SPU					1			1
7	Shackle	SPU					5		2	7
8	Polyester Sling	SPU							22	22
9	Beam Clamp	SPU							1	1
10										
11										
12										
13										
14										
15										

**Equipment Rental**

1	Water bag 3 tonnes	unit-day			und damage, s					
2	Water bag 12 tonnes	unit-day	1	1	1	1	1	1	1	7
3	Load Cell 5 tonnes	unit-day								
4	Load Cell 30 tonnes	unit-day	1	1	1	1	1	1	1	7
5	Wire rope tester	unit-day	1	1	1	1	1	1	1	7

**PROVISION**

7	Land Transportation	unit-day								
8	Meal allowance	man-day								

**Suhardi Maricen**  
Personnel In Attendance

**Isyudanto / Gunawan**  
Approved by PHM sites INS SPV