

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance: **Pambudhi Kristyanto**  
**Nico Achmad**  
**A. Fuad K**

Customer: **PERTAMINA HULU**  
**MAHAKAM**

Service Date: **20-Jan-2020**

Periode : **Des - Jan**

CRO No.: **8532803**

Rig/Well : **Handil**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			14-Jan	15-Jan	16-Jan	17-Jan	18-Jan	19-Jan	20-Jan	
1	Cargo Carrying Unit	HCA					4	5	3	12
2	Shackle	HCA					8		12	20
3	Wire Rope Sling 3-leg or 4-legs	HCA					1	1	3	5
4	Pad Eye	HCA						2		2
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										

Equipment Rental										
1	Water bag 3 tonnes	unit-day								
2	Water bag 12 tonnes	unit-day								
3	Load Cell 5 tonnes	unit-day								
4	Load Cell 30 tonnes	unit-day								
5	Wire rope tester	unit-day								

PROVISION										
7	Land Transportation	unit-day					1	1	1	3
8	Meal allowance	man-day					2	3	3	8

**Pambudhi Kristyanto**  
Personnel In Attendance

**Abu Khoiri/Ahmadan F**  
Approved by PHM sites INS SPV