

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance:   
 Period:   
 Day Rate:   
 Per Diem Rate :

Customer:   
 Contract / PO Non:   
 Rig / Well:

Date:   
 Our Ref:

Form No:

Billing Date	Rig / Loc*	Time*	Activity	Billing				Company Representative Signature
				Hour/s	WO Number	BORG	Segment	
9/15/2022	Duri	08.00 - 17.00	Standby waiting for Inspection	8	-	-	D&M	
9/16/2022	Duri	08.00 - 17.00	Standby waiting for Inspection	8	-	-	D&M	
9/17/2022	Duri	08.00 - 17.00	Full Body Inspection XOS8S 6-5/8" Reg Pin x NC50 Box, Lift Sub >= 7 in OD Steel	8	DD Tools_170922_PHR	-	D&M	
9/18/2022	Duri	08.00 - 17.00	Standby waiting for Inspection	8	-	-	D&M	
9/19/2022	Duri	08.00 - 17.00	Standby waiting for Inspection	8	-		D&M	
9/20/2022	Duri	08.00 - 17.00	Full Body Inspection BottlNeck Sub 6-5/8" Reg Pin x NC50 Box	8	DD Tools_200922_PHR		D&M	
* If Applicable TOTAL (Hours)				48				

\* If Applicable  
 Note:

Hajili  
 Personnel In Attendance