PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET

Personnel In Attendance	**Kelana syahputra**	Customer:	PHKT	Date :	20-Sep-23
Period:	September 2023	Contract/ PO Non:	4300012373	Our Ref:	
Day Rate:		Rig / Well:	Inspection Area - PT Citra Tubindo		
Per Diem Rate :				Form No. :	

Billing Date	Rig / Loc*	Time*	ACTIVITY	BILLING		
				Day	Mob/ Demob (USD)	Per diem (Day)
7-Sep-23	PHKT	08.00-17.00	Inspection Process Threading Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT	1		
8-Sep-23	PHKT	08.00-17.00	Inspection Process Threading Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT & Review Document Release Batch 1 RO-04	1		
9-Sep-23	PHKT	08.00-17.00	Inspection Process Threading & Bucking Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT	1		
10-Sep-23	PHKT	08.00-17.00	Inspection Process Bucking Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT	1		
11-Sep-23	PHKT	08.00-17.00	Inspection Process Threading Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT & Review Document Release Batch 1 RO-04	1		
12-Sep-23	PHKT	08.00-17.00	Inspection Process Threading Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT & Review Document Release Batch 1 RO-04	1		
13-Sep-23	PHKT	08.00-17.00	Inspection Process Bucking Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT	1		
14-Sep-23	PHKT	08.00-17.00	Inspection Process Bucking & External Coatiung Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT	1		
15-Sep-23	PHKT	08.00-17.00	Inspection Process Bucking & External Coatiung Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT	1		
16-Sep-23	PHKT	08.00-17.00	Inspection Process Bucking & External Coatiung Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT	1		
17-Sep-23	PHKT	08.00-17.00	Inspection Process Bucking & External Coatiung Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT	1		
18-Sep-23	PHKT	08.00-17.00	Inspection Process External Coatiung Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT	1		
19-Sep-23	PHKT	08.00-17.00	Inspection Process External Coatiung Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT ,Review Document Release Batch 2.	1		
20-Sep-23	PHKT	08.00-17.00	Inspection Process External Coatiung Pup Joint 3 1/2", 92,2 PPF,R-95,VAM TOP, 6,8,10 FT ,Review Document Release Batch 2.	1		
				14		
			TOTAL (USD)			
			GRAND TOTAL			

* - If Applicable

Personnel In Attendance | Contractor Representative | Rig Representative | The Company Representative