

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: **YUDHI PRASETYO**

Customer: **PERTAMINA HULU MAHAKAM**

Service Date: **24-Aug-2020**

Periode : **AGUSTUS**

CRO No.: **4200139211**

Rig/Well : **PECIKO**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL	
			SENIPAH	19-Aug	20-Aug	21-Aug	22-Aug	23-Aug	24-Aug		
1	SNATCH BLOCK	PECIKO		2	2	1			2	1	8
2	SHACKLE	PECIKO		1	2	3	1		4	6	17
3	PAD EYE	PECIKO		3	4			3			10
4	LIFTING FRAME WITH PAD EYE	PECIKO			2	2	1		1	1	7
5	SPREADER BAR	PECIKO			1	1	1				3
6	TURNBUCKLE					1				2	3
7											0
8											
9											0
Equipment Rental											
1	Water bag 3 tonnes	unit-day	0	0	0	0	0	0	0	0	0
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0	0	0	0
3	Load Cell 5 tonnes	unit-day	0	0	0	0	0	0	0	0	0
4	Load Cell 30 tonnes	unit-day	0	0	0	0	0	0	0	0	0
5	Wire rope tester	unit-day	0	0	0	0	0	0	0	0	0
PROVISION											
7	Land Transportation	unit-day	0	0	0	0	0	0	0	0	0
8	Meal allowance	man-day	0	0	0	0	0	0	0	0	0

YUDHI PRASETYO
Personnel In Attendance

IWAN S. / SETIONO

Approved by PHM sites INS SPV

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: **YUDHI PRASETYO**

Customer: **PERTAMINA HULU MAHAKAM**


Service Date: **31-Aug-2020**

Periode : **AGUSTUS**

CRO No.: **4200139211**

Rig/Well : **PECIKO**

No.	Service Description	Rig/Loc	Date of Inspection & Qty						TOTAL	
			25-Aug	26-Aug	27-Aug	SMK	SMK	SMK		31-Aug
1	PAD EYE	PECIKO	3	4					1	8
2	LIFTING FRAME WITH PAD EYE			3	1				1	5
3	SHACKLE			2	4				4	10
4	SNATCH BLOCK			2					1	3
5	SPREADER BAR			2					2	4
6	1 LEG WIRE ROPE SLING				2					2
7										0
8										
9										0
Equipment Rental										
1	Water bag 3 tonnes	unit-day	0	0	0	0	0	0	0	0
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0	0	0
3	Load Cell 5 tonnes	unit-day	0	0	0	0	0	0	0	0
4	Load Cell 30 tonnes	unit-day	0	0	0	0	0	0	0	0
5	Wire rope tester	unit-day	0	0	0	0	0	0	0	0
PROVISION										
7	Land Transportation	unit-day	0	0	0	0	0	0	0	0
8	Meal allowance	man-day	0	0	0	0	0	0	0	0


YUDHI PRASETYO
Personnel In Attendance

IWAN S. / SETIONO
Approved by PHM sites INS SPV

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: **YUDHI PRASETYO**

Customer: **PERTAMINA HULU MAHAKAM**

Service Date: **31-Aug-2020**

Periode : **AGUSTUS**

CRO No.: **4200139211**

Rig/Well : **South Mahakam**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			PECIKO	PECIKO	PECIKO	28-Aug	29-Aug	30-Aug	PECIKO	
1	OTHER BELOW THE HOOK LIFTING DEVICE	SOUTH MAHAKAM				4				4
2	PAD EYE					1	1	1		3
3	SHACKLE					14	7	16		37
4	TURNBUCKLE					1				1
5	SLEWING JIB DAVIT						4			4
Equipment Rental										
1	Water bag 3 tonnes	unit-day	0	0	0	0	0	0	0	0
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0	0	0
3	Load Cell 5 tonnes	unit-day	0	0	0	0	0	0	0	0
4	Load Cell 30 tonnes	unit-day	0	0	0	0	0	0	0	0
5	Wire rope tester	unit-day	0	0	0	0	0	0	0	0
PROVISION										
7	Land Transportation	unit-day	0	0	0	0	0	0	0	0
8	Meal allowance	man-day	0	0	0	0	0	0	0	0


YUDHI PRASETYO
 Personnel In Attendance

IWAN S. / SETIONO
 Approved by PHM sites INS SPV

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: **YUDHI PRASETYO**

Customer: **PERTAMINA HULU MAHAKAM**

Service Date: **7-Sep-2020**

Periode : **SEPTEMBER**

CRO No.: **4200139211**

Rig/Well : **PECIKO**

No.	Service Description	Rig/Loc	Date of Inspection & Qty						TOTAL	
			1-Sep	2-Sep	3-Sep	SMK	SMK	SMK		31-Aug
1	PAD EYE	PECIKO	3		4					7
2	LIFTING FRAME WITH PAD EYE			2	1					3
3	SHACKLE			12	4					16
4	SNATCH BLOCK			3						3
5	1 LEG WIRE ROPE SLING				2					2
6	TURNBUCKLE				2					2
7										0
8										
9										0
Equipment Rental										
1	Water bag 3 tonnes	unit-day	0	0	0	0	0	0	0	0
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0	0	0
3	Load Cell 5 tonnes	unit-day	0	0	0	0	0	0	0	0
4	Load Cell 30 tonnes	unit-day	0	0	0	0	0	0	0	0
5	Wire rope tester	unit-day	0	0	0	0	0	0	0	0
PROVISION										
7	Land Transportation	unit-day	0	0	0	0	0	0	0	0
8	Meal allowance	man-day	0	0	0	0	0	0	0	0

YUDHI PRASETYO
Personnel In Attendance

IWAN S. / SETIONO

Approved by PHM sites INS SPV

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET



Personnel In Attendance: **YUDHI PRASETYO**

Customer: **PERTAMINA HULU MAHAKAM**

Service Date: **7-Sep-2020**

Periode : **SEPTEMBER**

CRO No.: **4200139211**

Rig/Well : **South Mahakam**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			PECIKO	PECIKO	PECIKO	4-Sep	5-Sep	6-Sep	7-Sep	
1	SHACKLE	SOUTH MAHAKAM				12		8		20
2	OTHER BELOW THE HOOK LIFTING DEVICE					8				8
3	PAD EYE							5		
4										
5										
6										
7										
8										
9										0
10										0
11										0
Equipment Rental										
1	Water bag 3 tonnes	unit-day	0	0	0	0	0	0	0	0
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0	0	0
3	Load Cell 5 tonnes	unit-day	0	0	0	0	0	0	0	0
4	Load Cell 30 tonnes	unit-day	0	0	0	0	0	0	0	0
5	Wire rope tester	unit-day	0	0	0	0	0	0	0	0
PROVISION										
7	Land Transportation	unit-day	0	0	0	0	0	0	0	0
8	Meal allowance	man-day	0	0	0	0	0	0	0	0


YUDHI PRASETYO
 Personnel In Attendance

IWAN S. / SETIONO
 Approved by PHM sites INS SPV