

PT. INSPEKTINDO SINERGI PERSADA
SERVICES TIME SHEET





Personnel In Attendance:
 Period:
 Day Rate:
 Per Diem Rate:

Customer:
 Contract/ PO Non:
 Rig / Well:

Date:
 Our Ref:
 Form No.:


Billing Date	Rig / Loc*	Time*	ACTIVITY (Reguler)	BILLING				
				Hours	WO Number	BORG	Segment	Company Representative Signature
3-Apr-24	Manggar Base	08:00-16:00	Inspected of Bullnose - BULLNOSE REVERSE JETS - 6-1/2 OD - AH34390 - (MPI Inspection), Bullnose - BULLNOSE REVERSE JETS - 6-1/2 OD - AH34391- (MPI Inspection)	8	To Be Created		BDT	PT. SMITH TOOL INDONESIA
4-Apr-24	Manggar Base	08:00-16:00	Inspected of Reamer - Cutter Block 11625 - 5000236076-1 - (MPI Inspection), Reamer - Cutter Block 11625 - AH65139 / 02230K - (MPI Inspection),	8	WCD_BDT_CUTTERBLOCK			
5-Apr-24	Manggar Base	08:00-16:00	Inspected of Reamer - Cutter Block 11625 - 32103 J - (MPI Inspection), Reamer - Cutter Block 11625 - 78213H - (MPI Inspection),	8	To Be Created			
TOTAL (hours)				24				




 Saftiadi Akbar Cristoper
 Personnel In Attendance

* If Applicable



 Saftiadi
 ISP Inspector


 Geosha
 SLB Maintenance Technician


 Arif Rahmadit
 SLB Maintenance Supervisor