

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance:

**Yulius K**  
**Ermawan E**

Customer:

**PERTAMINA HULLU**  
**MAHAKAM**

Service Date:

**7-Jun-2022**

Periode :

**JUN - JUL**

CRO No.:

Rig/Well :

**PTK Tanjung Batu**

No.	Service Description	Rig/Loc	Date of Inspection & Qty							TOTAL
			1-Jun	2-Jun	3-Jun	4-Jun	5-Jun	6-Jun	7-Jun	
1	Transportation Containers		2	2	4	3	4	4		19
2	Wire Rope Sling 1-leg or 2-legs		15							15
3	Wire Rope Sling 3-leg or 4-legs			10					1	11
4	Shackle			8					12	20
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
<b>Equipment Used</b>										
1	Water bag 3 tonnes	unit-day	-	-	-	-	-	-	-	-
2	Water bag 15 tonnes	unit-day	-	-	-	-	-	-	-	-
3	Load Cell 5 tonnes	unit-day	-	-	-	-	-	-	-	-
4	Load Cell 30 tonnes	unit-day	-	-	-	-	-	-	-	-
5	Wire rope tester equipment	unit-day	-	-	-	-	-	-	-	-
<b>PROVISION</b>										
7	Land Transportation	unit-day	-	-	-	-	-	-	-	-
8	Daily Personnel allowance	man-day	2	2	2	2	2	2	2	12

**Yulius K**

Personnel In Attendance

Approved by PHM sites INS SPV

*[Signature]*  
19/06/22