

**PT. INSPEKTINDO SINERGI PERSADA**  
**SERVICES TIME SHEET**



Personnel In Attendance: **1. Gunawan R.**  
**2. Nico**

Customer: **PERTAMINA HULU MAHAKAM**

Service Date: **August 19, 2020**

Periode: **August 2020**

CRD No.:

Rig/Well: **PHM-Tanjung Batu**

No.	Service Description	Rig/Loc.	Date of Inspection & Qty							TOTAL
			19-Aug							
1	Cargo Carrying Unit (lifting set)	Tanjung batu	1							1
2	Polym...	Tanjung batu	1							1
<b>TOTAL</b>			<b>2</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>2</b>
<b>Equipment Rental</b>										
1	Water bag 3 tonnes	unit-day	0	0	0	0	0	0	0	0
2	Water bag 12 tonnes	unit-day	0	0	0	0	0	0	0	0
3	Load Cell 5 tonnes	unit-day	0	0	0	0	0	0	0	0
4	Load Cell 30 tonnes	unit-day	0	0	0	0	0	0	0	0
5	Wire rope tester	unit-day	0	0	0	0	0	0	0	0
<b>PROVISION</b>										
6	Land Transportation	unit-day	1	0	0	0	0	0	0	1
7	Meal allowance	man-day	2	0	0	0	0	0	0	2

**Gunawan R.**  
 Personnel In Attendance

**Juliana EMBERIUS**  
 I.S.A. / I.S.P. / I.S.V.  
 Approved by PHM Sites INS SPV