



REPORT OF NON-DESTRUCTIVE TEST

Magnetic Particle Inspection Liquid Penetrant Inspection 

Client	Division	Location
Schlumberger	Well Service	WCF Well Services Cementing-Duri Base
Date of this Examination	This Certificate Number	
06/04/2022	ISP.YM.WCF-AB-12/04/22.MPI	

ID No.	CTF41098Y0057 (WCF-AB-12)	Serial No.	-
Equipment Description	BULKER 98003 (FA 4207098003)		

Job Description To determining crack indication on surface areas by using Magnetic Particle Inspection.

Areas inspected				
-----------------	--	--	--	--

Equipment Details	Permanent Yoke Serial No. R0278A & R0278B Date Calibrated : Nov 2021 Calibrated Due Date : Nov 2022
Method	Visible
Chemical Used	Nabakem MP-35 & Nabakem SM-15
Material	Ferromagnetic
Preparation	Surface Cleaning
Test Procedure	ISP-SOP-NDT-03
Acceptance criteria	ASME Section 8
Pole Spacing	Max 150 mm
Dwell Time	N/A
Inspection result	No Found Indication During Time of Inspection (Accepted)

Inspector name & Signature	Date for Next Examination:
<p>Anton Baido Situmorang</p>	05/04/2023
Qualification of Inspector	
ANST Level II MT/PT, LGI	

